ASR-WITNESSING PART 3
USER GUIDE AGENCY

If you are NOT associating the ASW and the ASR records, then you can continue directly to page 11.





1. Verify that the "Copy Lab Control Number" is selected.

2. Click the next button.


Home
Previous
My Pages
Actions
Help
Log off
Sample Record
Copy Sample Record
Copy Sample Record
Progress:
Lab Control Number
Enter New Sample Info
Select Data To Copy
Select Sample Record Tests
Confirm
2 Enter New Sample Info:
Sample ID *
slade20230123071406
Lab Control Number
CNslade20230123070621
Sample Date
12/13/2022
1. Verify the Sample ID and Sample Date. They can both be changed if desired.
2. Click the next button.


Home
Previous
My Pages
Actions
Help
Log off
Sample Record
Copy Sample Record
Copy Sample Record
Progress:
Lab Control Number
Enter New Sample Info
Select Data To Copy
Select Sample Record Tests
Confirm
3 Select Data To Copy:
Select: All None
Copy Sample Record Remarks
Sources / Facilities
DSR Link
Sample Record Associations Other Than Destination Lab
Destination Lab
Contracts
Tests
Test Results
1. Deselect at a minimum "Destination Lab". You can deselect any other data you don't want copied to your sample record.
2. Click the next button.


Home
Previous
My Pages
Actions
Help
Log off
Sample Record
Copy Sample Record
Copy Sample Record
Progress:
Lab Control Number
Enter New Sample Info
Select Data To Copy
Select Sample Record Tests
Confirm
4 Select Sample Record Tests:
Sample Record Tests are not selected to copy.
Click the next button.


Home
Previous
My Pages
Actions
Help
Log off
Sample Record
Copy Sample Record
Copy Sample Record
Progress:
Lab Control Number
Enter New Sample Info
Select Data To Copy
Select Sample Record Tests
Confirm
5 Confirm:
Sample ID
slade20230123071650
Lab Control Number
CNslade20230123070621
Sample Date
12/13/2022
Data Selected For Copy
Copy Sample Record Remarks
Yes
Sources / Facilities
Yes
DSR Link
Yes
Sample Record Associations Other Than Destination Lab
Yes
1. Verify what data is being copied.
Destination Lab
No
Contracts
Yes
Tests
No
Test Results
No
Tests
No rows found matching criteria.
Test Results
No rows found matching criteria.
2. Click "Confirm".
Confirm


Home
Previous
My Pages
Actions
Help
Log off
Overview
Find Sample
Maintain Test Queue
Receive at Destination Lab
Receive at Lab Unit
Review Samples
Review Tests
Sample Record Summary
Save Complete
Sample Record: slade20230123071650
Save
General
Sample Location
Additional Information
Sources
Associations
Contract
Tests
Sample Record: Test(s) may not be assigned to Sample Records without a Destination Lab association on the Associations tab.
Sample ID*
slade20230123071650
Material Code - Name
SF
SuperPave Field Tests
Lab Reference Number
Lot/Heat Number
Lot/Heat Type
Represented Quantity
Represented Quantity Units
Begin typing to search or press Enter
Lab Control Number
CNslade20230123070621
Specimen Number
Remarks
0
Sample Date
12/13/2022
Sample Status
Pending
Sample Type
ASW - ASSURANCE WITNESS
Acceptance Method
ACCP - KDOT Tests And/Or Field Inspection
Authorized By
Authorized Date
Revised By
Link To Related Sample ID
Begin typing to search or press Enter
Linked Related Sample ID
Click the "Additional Information" tab.


Home
Previous
My Pages
Actions
Help
Log off
Overview
Find Sample
Maintain Test Queue
Receive at Destination Lab
Receive at Lab Unit
Review Samples
Review Tests
Sample Record Summary
Save Complete
Sample Record: slade20230123071650
4. Click "Save".
Save
General
Sample Location
Sources
Associations
Contract
Tests
5. Click the "General" tab.
Sample Record: Test(s) may not be assigned to Sample Records without a Destination Lab association on the Associations tab.
Sampler ID - Name
slade
Brent Slade
1. Remove the Sample ID - Name.
Witnessed By ID - Name
mweiser
Weiser Mark A
2. Remove the Witnessed By ID - Name.
Requested By
03 - District 3 Construction and Materials Engineer
Intended Use
Mix Design Type
Mix Design ID
Begin typing to search or press Enter
Buy America
CIT Witnessed
SF - HMA FIELD
3. Clear the CIT Witnessed box by selecting the blank row at the top of the drop down.
Created By
Created Date
01/23/2023 7:20:32 AM
Last Updated By
KDOTAD\slade
Last Updated Date
01/23/2023 7:20:32 AM
DWR Inspector
DSR Inspector
Limited Sample Access Last Modified By
Limited Sample Access Last Modified Date
Administrative Office Modified Date


Home
Previous
My Pages
Actions
Help
Log off
Overview
Find Sample
Maintain Test Queue
Receive at Destination Lab
Receive at Lab Unit
Review Samples
Review Tests
Sample Record Summary
Save Complete
Sample Record: slade20230123071650
Save
General
Sample Location
Additional Information
Sources
Associations
Contract
Tests
Sample Record: Test(s) may not be assigned to Sample Records without a Destination Lab association on the Associations tab.
Sample ID*
slade20230123071650
Material Code - Name
SF
SuperPave Field Tests
Lab Reference Number
Lot/Heat Number
Lot/Heat Type
Represented Quantity
Represented Quantity Units
Begin typing to search or press Enter
Lab Control Number
CNslade20230123070621
Specimen Number
Remarks
0
Sample Date
Sample Status
Pending
Sample Type
ASW - ASSURANCE WITNESS
Acceptance Method
ACCP - KDOT Tests And/Or Field Inspection
Authorized By
Authorized Date
Revised By
Link To Related Sample ID
Begin typing to search or press Enter
Linked Related Sample ID
1. Remove the Material Code - Name.
2. Click "Save".
Repeat Steps 1 and 2 until the Material Code - Name is gone after saving.


Home
Previous
My Pages
Actions
Help
Log off
Show Help
Overview
Find Sample
Maintain Test Queue
Receive at Destination Lab
Receive at Lab Unit
Review Samples
Review Tests
Sample Record Summary
Save Complete
Sample Record: slade20230123071650
Save
General
Sample Location
Additional Information
Sources
Associations
Tests
Sample Record: Test(s) may not be assigned to Sample Records without a Destination Lab association on the Associations tab.
Sample ID*
slade20230123071650
Remarks
0
Material Code - Name
Begin typing to search or press Ente
Lab Reference Number
Lot/Heat Number
Lot/Heat Type
Represented Quantity
Represented Quantity Units
Begin typing to search or press Enter
Lab Control Number
CNslade20230123070621
Specimen Number
mple Date
/13/2022
Sample Status
Pending
Sample Type
ASW - ASSURANCE WITNESS
Acceptance Method
ACCP - KDOT Tests And/Or Field Inspection
Authorized By
Authorized Date
Revised By
Link To Related Sample ID
Begin typing to search or press Enter
Linked Related Sample ID
6. Click the "Sources" tab.
3. Enter the material code for the material being tested.
1. Enter the date the material was sampled.
2. Change from "ASW" to "ASR".
4. Enter the quantity represented by the test.
5. Enter the unit of measure for the quantity.


Home
Previous
My Pages
Actions
Help
Log off
Overview
Find Sample
Maintain Test Queue
Receive at Destination Lab
Receive at Lab Unit
Review Samples
Review Tests
Sample Record Summary
Save Complete
Sample Record: slade20230123071650
Save
General
Sample Location
Additional Information
Sources
Associations
Contract
Tests
Sample Record: Test(s) may not be assigned to Sample Records without a Destination Lab association on the Associations tab.
Primary Source/Facility
Select Primary Source...
Select Primary Facility...
Source ID - Source Name
Facility ID - Facility Name
Click "Select Primary Source".
Source City
Facility City
Source Type
Facility Type
Source Location Description
Facility Location Description
SMFMI Name
Begin typing to search or press Enter
Brand Name
Begin typing to search or press Enter
Additional Sources
Type search criteria or press Enter
Advanced
Select Sources...
0 marked for deletion
0 changed
No rows found matching criteria.


Select Primary Source
Type search criteria or press Enter
Advanced
Enter search criteria above to see results
or
Show first 10
Either search for the material source or click "Show first 10".
0 selected
Add to Sample Record
Source ID - Source Name
Facility ID - Facility Name
Source City
Facility City
Source Type
Facility Type
Source Location Description
Facility Location Description
SMFMI Name
Begin typing to search or press Enter
Brand Name
Begin typing to search or press Enter
Additional Sources
Type search criteria or press Enter
Advanced
Select Sources...
0 marked for deletion
0 changed
No rows found matching criteria.


Select Primary Source
venture
Advanced
Showing 6 of 6
1 selected
Source ID - Name
Source Type
Source City
Location Description
CC081700 - VENTURE CORPORATION (GREAT BEND,KS)
P - PRODUCER
GREAT BEND
CC081704 - VENTURE CEDAR RAPIDS 8828 (OWNER #4)
M - MIX PLANT
GREAT BEND
CC081702 - VENTURE CEDAR RAPIDS 7224 (OWNER #2)
M - MIX PLANT
GREAT BEND
CC081706 - VENTURE BOEING 400 (OWNER #2)
M - MIX PLANT
GREAT BEND
GREAT BEND
CC081705 - VENTURE CMI- PV10 (OWNER #5)
M - MIX PLANT
GREAT BEND
1. Select the material source from the list.
2. Click "Add to Sample Record".
Add to Sample Record
SMFMI Name
Begin typing to search or press Enter
Brand Name
Begin typing to search or press Enter
Additional Sources
Type search criteria or press Enter
Advanced
Select Sources...
0 marked for deletion
0 changed
No rows found matching criteria.


Home
Previous
My Pages
Actions
Help
Log off
Overview
Find Sample
Maintain Test Queue
Receive at Destination Lab
Receive at Lab Unit
Review Samples
Review Tests
Sample Record Summary
There are unsaved changes.
Sample Record: slade20230123071650
Save
General
Sample Location
Additional Information
Associations
Contract
Tests
Sample Record: Test(s) may not be assigned to Sample Records without a Destination Lab association on the Associations tab.
Primary Source/Facility
Select Primary Source...
Select Primary Facility...
Facility ID - Facility Name
CC081704 - VENTURE CEDAR RAPIDS 8828 (OWNER #4)
Source City
Facility City
GREAT BEND
Source Type
Facility Type
M - MIX PLANT
Source Location Description
Facility Location Description
SMFMI Name
Begin typing to search or press Enter
Brand Name
Begin typing to search or press Enter
Additional Sources
Type search criteria or press Enter
Advanced
Select Sources...
0 marked for deletion
0 changed
No rows found matching criteria.
1. Click "Save".
2. Click the "Sample Location" tab.

Modify any of the Sample Location information as needed and then click "Save" if anything was changed.



Click the "Additional Information" tab.


Home
Previous
My Pages
Actions
Help
Log off
Overview
Find Sample
Maintain Test Queue
Receive at Destination Lab
Receive at Lab Unit
Review Samples
Review Tests
Sample Record Summary
Save Complete
Sample Record: slade20230123071650
Save
General
Sample Location
Additional Information
Sources
Associations
Contract
Sample Record: Test(s) may not be assigned to Sample Records without a Destination Lab association on the Associations tab.
Sampler ID - Name
Begin typing to search or press Enter
Witnessed By ID - Name
Begin typing to search or press Enter
Requested By
03 - District 3 Construction and Materials Engineer
Intended Use
Mix Design Type
Mix Design ID
Begin typing to search or press Enter
Buy America
CIT Witnessed
Created By
Created Date
01/23/2023 7:20:32 AM
Last Updated By
KDOTAD\slade
Last Updated Date
01/23/2023 7:28:15 AM
DWR Inspector
st Modified By
Limited Sample Access Last Modified Date
Administrative Office Modified By
Administrative Office Modified Date
1. Enter the District person performing the test.
2. If testing a material with a mix design, select the Mix Design Type from the drop down.
3. If testing a material with a mix design, enter the Mix Design ID.
4. Click "Save".
5. Click the "Associations" tab.


Home
Previous
My Pages
Actions
Help
Log off
Overview
Find Sample
Maintain Test Queue
Receive at Destination Lab
Receive at Lab Unit
Review Samples
Review Tests
Sample Record Summary
Save Complete
Sample Record: slade20230123071650
Save
General
Sample Location
Additional Information
Sources
Associations
Contract
Tests
Sample Record: Test(s) may not be assigned to Sample Records without a Destination Lab association on the Associations tab.
Type search criteria or press Enter
Advanced
New
Click "New".
0 added
0 marked for deletion
0 changed
No rows found matching criteria.


Home
Previous
My Pages
Actions
Help
Log off
Overview
Find Sample
Maintain Test Queue
Receive at Destination Lab
Receive at Lab Unit
Review Samples
Review Tests
Sample Record Summary
Save Complete
Sample Record: slade20230123071650
3. Click "Save".
Save
General
Sample Location
Additional Information
Sources
Associations
Contract
Tests
Sample Record: Test(s) may not be assigned to Sample Records without a Destination Lab association on the Associations tab.
Type search criteria or press Enter
Advanced
New
1 added
0 marked for deletion
0 changed
Association Type*
Association Value*
Begin typing to search or press Enter
1. Select "Destination Lab" from the drop down.
2. Enter District Lab performing the test.
4. Click the "Contract" tab.


Home
Previous
My Pages
Actions
Help
Log off
Overview
Find Sample
Maintain Test Queue
Receive at Destination Lab
Receive at Lab Unit
Review Samples
Review Tests
Sample Record Summary
Save Complete
Sample Record: slade20230123071650
Save
General
Sample Location
Additional Information
Sources
Associations
Contract
Tests
Type search criteria or press Enter
Advanced
Select Contract Project Items...
Click "Select Contract Project Items".
0 marked for deletion
0 changed
No rows found matching criteria.


Select Contract Project Item Line Numbers
Type search criteria or press Enter
Advanced
Select: All None
0 selected
Enter search criteria above to see results
or
Show first 10
Either search for your contract or click "Show first 10".
Save
Home
Log off
Overview
General
Sample Loc
Additional I
Sources
Associations
Contract
Tests
changed


Home
Log off
Overview
Sample
General
Sample Lo
Additional I
Sources
Association
Contract
Tests
Select Contract Project Item Line Numbers
521052373
Advanced
Showing 5 of 5
Select: All | None
1 selected
Contract
Project
Project Item Line Nbr
Material Set
521052373 - MILLING AND OVERLAY
KA 6068-01
10 - HMA OVERLAY (SR-12.5A) (PG 70-28 RCI)
MIGRATION 060290 90 Set A 521052373
521052373 - MILLING AND OVERLAY
KA 6068-01
14 - MATERIAL FOR HMA PATCHING (SET PRICE
MATERIAL FOR HMA PATCHING
521052373 - MILLING AND OVERLAY
KA 6068-01
8 - HMA OVERLAY (SR-12.5A) (PG 76-22)
HMA OL (SR-12.5A) (PG 76-22)
521052373 - MILLING AND OVERLAY
KA 6068-01
9 - HMA OVERLAY (SR-12.5A) (PG 64-22) (SHOU
HMA OL (SR-12.5A) (PG 64-22)
52
10 - HMA OVERLAY (SR-12.5A) (PG 70-28 RCI)
HMA OL (SR-12.5A) (PG 70-28)(RCI)
1. Select your contract line item(s).
2. Click "Save".
Save


Home
Previous
My Pages
Actions
Help
Log off
Overview
Find Sample
Maintain Test Queue
Receive at Destination Lab
Receive at Lab Unit
Review Samples
Review Tests
Sample Record Summary
Save successful
Sample Record: slade20230123071650
Save
General
Sample Location
Additional Information
Sources
Associations
Contract
Tests
Material
HMA_12.5A - Hot Mix Asphalt SR/SM-12.5A
Sample Type
ASR - ASSURANCE REPLICATE
Type search criteria or press Enter
Advanced
Assign Tests
2. Click "Assign Tests".
0 marked for deletion
0 changed
No rows found matching criteria.
1. Click the "Tests" tab.


Home
Previous
My Pages
Actions
Help
Log off
Sample Record
Maintain Test Queue
Assign Sample Record Test
Assign Sample Record Test
Progress:
Review Required Tests
Select Default Tests
Select Optional Tests
Add Test Runs and Confirm
1 Review Required Tests:
No rows found matching criteria.
Click the next button.


Home
Previous
My Pages
Actions
Help
Log off
Sample Record
Maintain Test Queue
Assign Sample Record Test
Assign Sample Record Test
Progress:
Review Required Tests
Select Default Tests
Select Optional Tests
Add Test Runs and Confirm
2 Select Default Tests:
Type search criteria or press Enter
Advanced
Showing 2 of 2
Select: All | None
2 selected
Test Method
Test Description
Lab Unit
Autofinalize
Test Runs
HMA Mix Analysis
HMA Mix Analysis (KT-58, KT-15-III, KT-39, KT-57, KT-
District 3 Materials Lab
Yes
1
Misc. Aggregate Test
Misc Aggr Tests for HMA (KT-31, KT-50, KT-55, KT-57,
District 3 Materials Lab
Yes
1
1. Select the Test(s) you are performing.
2. Click the next button.


Home
Previous
My Pages
Actions
Help
Log off
Sample Record
Maintain Test Queue
Assign Sample Record Test
Assign Sample Record Test
Progress:
Review Required Tests
Select Default Tests
Select Optional Tests
Add Test Runs and Confirm
3 Select Optional Tests:
Type search criteria or press Enter
Advanced
Select: All None No rows found matching criteria.
0 selected
Click the next button.


Home
Previous
My Pages
Actions
Help
Log off
Sample Record
Maintain Test Queue
Assign Sample Record Test
Assign Sample Record Test
Progress:
Review Required Tests
Select Default Tests
Select Optional Tests
Add Test Runs and Confirm
4 Add Test Runs and Confirm:
Required Tests
0 changed
No rows found matching criteria.
Selected Default Tests
0 changed
Test Method
Test Description
Lab Unit
Autofinalize
Test Runs
HMA Mix Analysis
HMA Mix Analysis (KT-58, KT-15-III, KT-39, KT-57, KT-34
District 3 Materials Lab
Yes
1
Misc. Aggregate Test
Misc Aggr Tests for HMA (KT-31, KT-50, KT-55, KT-57, K
District 3 Materials Lab
Yes
1
Selected Optional Tests
0 changed
No rows found matching criteria.
1. Verify the test(s) selected.
2. Click "Confirm".
Confirm


Home
Previous
My Pages
Actions
Help
Log off
Overview
Find Sample
Maintain Test Queue
Receive at Destination Lab
Receive at Lab Unit
Review Samples
Review Tests
Sample Record Summary
Save Complete
Sample Record: slade20230123071650
Save
General
Sample Location
Additional Information
Sources
Associations
Contract
Tests
Material
HMA_12.5A - Hot Mix Asphalt SR/SM-12.5A
Sample Type
ASR - ASSURANCE REPLICATE
Type search criteria or press Enter
Advanced
Showing 2 of 2
Assign Tests
0 marked for deletion
0 changed
Test Number
Test Method
Destination Lab
Lab Unit
MAA
Test Inst
Required
Default
1.0
HMA Mix Analysis
District 3 Materials
District 3 Materials La
1
No
Yes
Test Status
Reference Specification Selected
05 - Test Assigned
No
1. Click the row action button.
1.0
Misc. Aggregate Test
District 3 Materials
District 3 Materials La
Yes
1
No
Yes
05 - Test Assigned
No
Actions
Delete
Exclude from Search Results
Open
Tasks
Add Test Run
Generate Test Results Comparison
Views
Attachments (0)
HMA Superpave v3
Links
Tracked Issues
2. Click the Agency View for the test you are running.

Enter the test data in Agency View for all replicate test(s). Pages 29-32 are the same screen.



Home | Previous | My Pages | Actions | Help | Log off

Sample Record Test

Agency View Summary

HMA Superpave v.3 — Print | Save

0 changed

Quality Control/Verification Sublot/Lot Volumetrics Report

Project Number:	I070-091 KA 6068-01	**Contract No.**	521052373	**Sample ID**	slade20230123071650
Mix Type:	Hot Mix Asphalt SR/SM-12.5A	**Location:**		**Tests performed by:**	Begin typing to search or press Enter
Design Lab No.:	3g22010A	**Represented Qty (Tons)**		**Certified Inspector #:**	
Lot/Sublot #:					
Date Sampled:		**Remarks:**			
PG Grade	021PG5828				

0 changed

Mix Blend

Mix Design: **3g22010A**

Material Code	Source	Source Name	Local Name	%	Gsb	% / Gsb
AGGHMA_CG-1	00835801	HUBER SAND COMPANY (SAND PIT) (HAMILTON COUNTY)	huber		2.562	
AGGHMA_CG-3A	00835801	HUBER SAND COMPANY (SAND PIT) (HAMILTON COUNTY)	huber		2.593	
AGGHMA_CG-2A	00835801	HUBER SAND COMPANY (SAND PIT) (HAMILTON COUNTY)	huber		2.605	
AGGHMA_CG-2	00835801	HUBER SAND COMPANY (SAND PIT) (HAMILTON COUNTY)	huber		2.607	
AGGHMA_SSG-2	00835801	HUBER SAND COMPANY (SAND PIT) (HAMILTON COUNTY)	huber		2.603	
AGGHMA_RAP			Oakley APAC		2.617	
Total Aggregate				0		0.000

Combined Aggregate Gsb

021PG5828	00002407	SUNCOR ENERGY (Denver Terminal)(COMMERCE CITY, CO)	denver		**Target AC**
Gb of added AC				1.0280	

Additive	Source	Source Name	Product	%
Warm Mix	00069701	ARR MAZ CUSTOM CHEMICALS (MULBERRY, FL)	ultra P	
Anti-Strip				
Rejuvenator				

KT-39: HMA, GMM, Rice THEORETICAL MAX

	A	B
Flask used Yes/No		
Mass Of Sample and Container (g)		
Mass Of Container (g)		
Mass of Sample (g)		
Water Temperature (°F)		
Container & Sample & Water (g)		
Mass of Container & Water (g)		
Mass Sample in Water (g)		
Max. Sp. Gr. (Gmm)		
Average Gmm		

0 changed

KT-58 (Gyratory Plugs)

Nini Revolutions:	6	
Ndes Revolutions;	50	
Nmax Revolutions;	75	Compacting Temp. Range (F)

	A	B
Mold. Temp. (F)		
Ht.@Nini (mm)		
Ht.@Ndes (mm)		
Ht.@Nmax (mm)		
Mass In Air (Dry)		
Mass In Water(Sat.)		
Mass In Air(Sat.)		
Sp.Gr.(Nmax)		
% Gmm(Nmax)		
Sp.Gr.(Ndes)		
% Gmm(Ndes)		
Sp.Gr.(Nini)		
% Gmm(Nini)		

0 changed

KT-57 (Ignition Oven Burn-off)

Wet Sample Mass (g)	
Mass of Moisture in Mix (g)	0.00
Percent Moisture in Mix (%)	0.00
Sample & Basket Mass (g)	
Basket Mass (g)	
Mass of Sample (g)	
Aggregate & Basket Mass (g)	
Mass Loss (g)	
Correction Factor (%)	
%AC (Corrected)	

0 changed

Sieve Analysis

Sample Dry Mass (g)	
Sample Mass After Wash (g)	

Blank1

Sieve	Grams Retained	% Retained
1 1/2"		
1		
3/4		
1/2		
3/8		
#4		
#8		
#16		
#30		
#50		
#100		
#200		
Pan		
Test Acceptability		
-#200		
Surface Area	0.00	

0 changed

Recap of Mix Properties

Target % AC in the Mix	

% AC by Mass of Mix	
% Aggr. by Mass of Mix	
Sp. Gr. of AC	
Bulk Sp. Gr. of Aggr.	
Max. Sp. Gr.	
Percent Passing the #200 Sieve	
Surface Area	0.00
Bulk Sp. Gr. of Mix	
Eff. Sp. Gr. of Aggr.	
Absorbed % AC	
Eff. Asphalt Content	
% VMA	
% Air Voids	
% VFA	
Eff. Film Thickness	
Dust/Binder Ratio	
% AC(Dev. from Target)	
% Gmm @ Nini	
% Gmm @ Nmax	


Home
Previous
My Pages
Actions
Help
Log off
Sample Record Test
2. Click "Sample Record Test".
There are unsaved changes.
HMA Superpave v.3
1. Once all the data has been entered click "Save".
Print
Save
1 changed
Quality Control/Verification Sublot/Lot Volumetrics Report
Project Number:
I070-091 KA 6068-01
Contract No.
521052373
Sample ID
slade20230123071650
Mix Type:
Hot Mix Asphalt SR/SM-12.5A
Location:
M - Mainline
Tests performed by:
Weiser
Mark
Design Lab No.:
3g22010A
Represented Qty (Tons)
1.00
Certified Inspector #:
000305007
Lot/Sublot #:
01C
Date Sampled:
11/13/2022
Remarks:
Replicate Testing of Back Half
PG Grade
021PG5828
1 changed
Mix Blend
Mix Design:
3g22010A
Material Code
Source
Source Name
Local Name
%
Gsb
% / Gsb


Home
Previous
My Pages
Actions
Help
Log off
Enter Test Results
Maintain Test Queue
Review Samples
Review Tests
Sample Record
Sample Record Test Summary
Sample Record ID: slade20230123071650
Save
Test Number: 1.0 Test Method - Description: HMA Mix Analysis - HMA Mix Analysis (KT-58, KT-15-III, KT-39, KT-57, KT-34)
General
Testers
Reference Specifications
Retests
Click the "Testers" tab.
Test Information
Test Status
05 - Test Assigned
Remarks
0
Priority
Planned Test Start Date
Default Test
Yes
Test Start Date
01/23/2023
Required Test
No
Estimated Completion Date
Due Date
Actual Completion Date
Sample Information
Sample Type
ASR - ASSURANCE REPLICATE
Contract ID
521052373
Lab Unit
District 3 Materials Lab - District 3 Materials Lab Unit
Source
CC081704 - VENTURE CEDAR RAPIDS 8828 (OWNER #4)
Lab Reference Number
Sample Date
Test Result Value
Sample Record Remarks
0


Home
Previous
My Pages
Actions
Help
Log off
Enter Test Results
Maintain Test Queue
Review Samples
Review Tests
Sample Record
Sample Record Test Summary
Save Complete
Sample Record ID: slade20230123071650
Save
Test Number: 1.0 Test Method - Description: HMA Mix Analysis - HMA Mix Analysis (KT-58, KT-15-III, KT-39, KT-57, KT-34)
General
Testers
Reference Specifications
Retests
Type search criteria or press Enter
Advanced
New
2 added
0 marked for deletion
0 changed
Begin typing to search or press Enter
Tester ID*
Tester Action
Begin typing to search or press Enter
3. Click "Save".
1. Enter a person performing an action on the test.
2. Enter the action the person performed.
Repeat Steps 1 and 2 for each person performing an action.


Home
Previous
My Pages
Actions
Help
Log off
Enter Test Results
Maintain Test Queue
Review Samples
Review Tests
Sample Record
Sample Record Test Summary
Save Complete
1. Click the component action button.
Sample Record ID: slade20230123071650
Test Number: 1.0 Test Method - Description: HMA Mix Analysis - HMA Mix Analysis (KT-58, KT-15-III, KT-39, KT-57, KT-34)
Actions
There are no actions available.
Tasks
Generate Test Results Comparison
Mark Test Complete
Views
Attachments (0)
HMA Superpave v3
Issues
Links
General
Testers
Retests
3. Click the "General" tab.
Type search criteria or press Enter
Advanced
Showing 2 of 2
2. Click "Mark Test Complete".
New
Tester ID*
Tester Action
mweiser
Mark A Weiser
Performed Tests
mweiser
Mark A Weiser
Entered Test Results


Home
Previous
My Pages
Actions
Help
Log off
Enter Test Results
Maintain Test Queue
Review Samples
Review Tests
Sample Record
Sample Record Test Summary
Save Complete
Sample Record ID: slade20230123071650
Save
Test Number: 1.0 Test Method - Description: HMA Mix Analysis - HMA Mix Analysis (KT-58, KT-15-III, KT-39, KT-57, KT-34)
General
Testers
Reference Specifications
Retests
5. Click "Sample Record".
4. Click "Save".
Remarks
40 - Test Complete
0
Priority
Planned Test Start Date
Default Test
Yes
Test Start Date
01/23/2023
Required Test
No
Estimated Completion Date
Due Date
Actual Completion Date
01/23/2023
Sample Information
Sample Type
ASR - ASSURANCE REPLICATE
Contract ID
521052373
Lab Unit
District 3 Materials Lab - District 3 Materials Lab Unit
Source
CC081704 - VENTURE CEDAR RAPIDS 8828 (OWNER #4)
Lab Reference Number
Sample Date
Test Result Value
1. Select the appropriate test result from the drop down.
Yes
Sample Record Remarks
Type
Remark
Additional Test Information
Retest Test
No
Reportable
Yes
Number of Retests
Updateable
Yes
Retest Requested
No
Test Requeued
No
Remarks
Type *
Remark *
2. Select "Test Result Value" from the drop down.
3. Enter a test result.
The sample is now Authorized.

If you want to add the Field's test data as an attachment, follow the steps on pages 38-44.




Home
Previous
My Pages
Actions
Help
Log off
Attachments Overview
Attachments For Sample Record
Save
Type search criteria or press Enter
Advanced
Select File...
Click "Select File".
0 marked for deletion
0 changed
Expand All
No rows found matching criteria.


Home
Previous
My Pages
Actions
Help
Log off
Attachments Overview
There are unsaved changes.
Attachments For Sample Record
Save
Click "Save".
Type search criteria or press Enter
Advanced
Select File...
April 2021 SpG List.pdf 401351 bytes
0 marked for deletion
0 changed
Expand All
Filename
Historical Report
Size (kb)
Additional Roles Count
April 2021 SpG List.pdf
0
Description
Attorney/Client Privilege


Home
Previous
My Pages
Actions
Help
Log off
Attachments Overview
Save Complete
Attachments For Sample Record
Save
Type search criteria or press Enter
Advanced
Showing 1 of 1
Select File...
0 marked for deletion
0 changed
Expand All
Filename
Historical Report
Size (kb)
Additional Roles Count
April 2021 SpG List.pdf
No
391
0
Description
Attorney/Client Privilege
1. Click the row action button.
Actions
Delete
Exclude from Search Results
Select Roles...
2. Click "Select Roles".


Select Roles
Type search criteria or press Enter
Advanced
Select: All None
0 selected
Enter search criteria above to see results
or
Show first 10
Either search for the role(s) or click "Show first 10".
Add to Attachment
Home
Log off
Expand All
April 2021 SpG List.pdf
No
391 0
Description
Attorney/Client Privilege
No rows found matching criteria.


Home
Log off
Select Roles
mater
Advanced
Showing 3 of 3
Select: All None
2 selected
Role ID
Role Description
MATERIALUSER
SAMPLE ROLE for Material User (DO NOT MODIFY)
MATERIALUSER_KS
KS ROLE for Material User
MATERIALUSER_KS_SUPERVISOR
KS ROLE for Material User Supervisor
1. Select the role(s) you want to have access to your attachment.
2. Click "Add to Attachment".
Add to Attachment
Expand All


Home
Previous
My Pages
Actions
Help
Log off
Attachments Overview
There are unsaved changes.
Attachments For Sample Record
Save
Click "Save".
Type search criteria or press Enter
Advanced
Showing 1 of 1
Select File...
0 marked for deletion
0 changed
Expand All
Filename
Historical Report
Size (kb)
Additional Roles Count
April 2021 SpG List.pdf
No
391
0
Description
Attorney/Client Privilege
Additional Role
Role Description
MATERIALUSER_KS
KS ROLE for Material User
MATERIALUSER_KS_SUPERVISOR
KS ROLE for Material User Supervisor