FASTNERS TYPE A CERTIFICATION USER GUIDE

Home	TEST ENVIRONMENT Verify Role.	Actions Help
Switch Role	Instruction Person Overview Reference Data Ser (Copied from MATERIALUSER) Image: Construction Image: Construction Image: Contract Administration Image: Contract Administration Image: Contract Claims Image: Contract Claims Image: Contract Permits Image: Contract Specific Authorities Image: Contract Specific Authorities Image: Contract Time Image: Contract Vendor Assets Image: Contract Vendor Ass	
Review Samples Review Tests Person Overview	Qualifications User Reference Employee	Save 🔻 ?
Enter search criteria above to see results or Show	v first 10	0 marked for deletion 0 changed

✓ Reference Data	•
Administrative Offices	▼
Alternate Test Workflow	$\overline{\mathbf{v}}$
Code Tables	· · · · · · · · · · · · · · · · · · ·

Home Previous My Pages TEST ENVIRONMENT

Actions Help Log off

On this page: Materials Materials Worksheets Construction Person Overview Reference Data

PROJECT KDOT role for Materials User (Copied from MATERIALUSER)

✓ Materials	?	✓ Construction	?
Acceptance Actions	•	Change Order	V
Action Relationships	•	Contract Administration	•
Daily Source Reports	•	Contract Claims	•
Find Sample		Contract Permits	•
Mix Design	•	Contract Progress	•
Product Group Sample Reviewer Assignment	•	Contract Specific Authorities	•
Sample Records Click "Sample Records".	•	Contract Time	•
v Materials Workshoots	0	Contract Vendor Assets	•
	U	Contractor Evaluation	•
Enter lest Results	_	Meetings	•
Maintain Test Queue		Payment Estimate Accounting	•
Receive Sample at Destination Lab		Payment Estimate Approval Decisions	
Receive Sample at Lab Unit		Payment Estimates	
Review Samples		·	
Review Tests	•		

✓ Person Overview							
		Qualifications	;	User		Reference Er	nployee
Q Type search criteria or press Enter	Advanced	No Filter	•	No Filter	•	No Filter	•

0 marked for deletion 0 changed

Enter search criteria above to see results or Show first 10

✓ Reference Data	?
Administrative Offices	•
Alternate Test Workflow	•
Code Tables	· · · · · · · · · · · · · · · · · · ·

Home Previous My Pages TEST ENVIRONMENT		Actions Help	U Log off
Sample Record Overview			
✓ Sample Record Overview	1. Click the component action button.	Save	- ?
Q Type search criteria or press Enter System Default	2. Click "Add". Actions	3	K
Enter search criteria above to see results or Show first 10		0 marked for deletion 0	changed

Home Previous My Pages	TEST ENVIRONMENT			Actions Help Log off
Overview				
Add Sample Record				
✓ Add Sample Record				
General Sample Location	Sample ID *		Sample Date	1. Enter the date the material was sampled.
Additional information Sources actilities	Q Begin typing to search or press Enter	2. Enter the material	Sample Status	
8. Click "Sample Location".	Lab Control Number	being tested.	Sample Type	3. Select "CTA - CERTIFICATION TYPE
	Lab Reference Number		Acceptance Method	A" from the drop down.
	Lot/Heat Number		Authorized By	4. Select "ACCP - KDOT Tests And/Or Field Inspection" from the drop down
	Lot/Heat Type		Authorized Date	
	Specimen Number		Revising Sample ID	
	Sample Size		Revised By	
	Sample Size Units		Link To Related Sample ID Q Begin typing to search of	or press Enter
5. Enter the quantity	Represented Quantity		Linked Related Sample ID	
represent by the test.	Represented Quantity Units			
	Q Begin typing to search or press Enter	6. Enter the unit of meas	ure for the ma	aterial.
	✓ Remarks			
	Туре*	Remark *		
	•			Q

Home				Actions Help Log off
Overview Find Sample Maintain Test Queue Sample Record Summary	Receive at Destination Lab Re	ceive at Lab Unit Review Samples Review Tests	X	
 ✓ Sample Record: slade20220328114 General Sample Location Additional Information Sources Associations 4. Click "Additional Information". Tests	302 Sample Record: Test(s) may not Sampled From Sample Origin Geographic Area Latitude Longitude Distance From Grade Distance From Grade	be assigned to Sample Records without a Destination Lab association Image: Im	3. Click "Sa a on the Associations tab. Reference ere the material was sampled from Station Station Plus area from Ifset Distance Offset Direction Elevation Comments	ve". Save v ()
	Sampled Ledge Name Location Start Coordinate X		End Coordinate X	



Actions Help Log off

Sample Record Summary	Save Complete	×
✓ Sample Record: slade20220328114	302	5. Click "Save".
General	Sample Record: Test(s) may not be assigned to Sample Records without a D	estination Lab association on the Associations tab.
Sample Location Additional Information	Sampler ID - Name	Created By
Additional Information Sources Assolutions Contlact 6. Click "Sources".	Begin typing to search or press Enter Witnessed By ID - Name Begin typing to search or press Enter Requested By Performed from Intended Use Mix Design Type Image: Search or press Enter Buy America A. Click the "Buy America Buy USA Requirements Image: Search or press Enter	r who sampled the material. Created Date 0928/2022 11:43:02 AM Last Updated By DOTADIslade Last Updated Date 0928/2022 11: Cast Updated Date 0928/2022 11: Cast Updated Date 0928/2022 11: Cast Updated Date 0928/2022 11: Cast Updated Date DSR Inspector DSR Inspector Limited Sample Access Last Modified By Limited Sample Access Last Modified Date
	CIT Witnessed	Administrative Office Modified By





Sample Record Summary	Save Complete	×	
✓ Sample Record: slade202203281143	302		Save 🔻 ?
General	Sample Record: Test(s) may not be assigned to Sample Records without a Destination	Lab association on the Associations tab.	
Sample Location	✓ Primary Source/Facility		
Additional Information	Select Primary Source Select Primary Facility		
Sources	Source ID - Source Name	Facility ID - Facility Name	
Associations Contract Contract	lect Primary Source".	- Eacility City	
Tests	Source ony	ruomy ony	
	Source Type	Facility Type	
	Source Location Description	Facility Location Description	
	SMFMI Name Q Begin typing to search or press Enter V Additional Sources		
	Q Type search criteria or press Enter 🥒 Advanced		
	Select Sources		0 marked for deletion 0 changed
	No rows found matching criteria.		
	✓ Additional Facilities		

Home Select Primary Source			▼ ? Ú × Log off
Overview F Sample Q Sample Q Type search criteria or press Enter search criteria above to see Sample C Additional I	s Enter Advanced e results or Show first 10	Either search for the source name or click "Show first 10".	0 selected
Sources	Source ID - Source Name	Facility ID - Facility Name	
Associations Contract Tests	- Source City	- Facility City	
	Source Type	Facility Type	
	Source Location Description	Facility Location Description	
	SMFMI Name Q Begin typing to search or press Enter V Additional Sources		
	Q Type search criteria or press Enter Image: Comparison of the press Enter Select Sources		0 marked for deletion 0 changed
	No rows found matching criteria.		

Home Select Primary Source					v C2 U × Log off
Overview F Sample I Sample I General Sample Lov Additional I Sources	Advanced Showing 1 of 1 le	1. Select the Source Type P - PRODUCER	Source City ST. LOUIS	Location Description	1 selected
Association Contract Tests	source city		2. Click "Add Facility of	I to Sample Record".	Add to Sample Record
	Source Type		Facility Ty	уре	
	Source Location Description		Facility L	ocation Description	
	SMFMI Name Q Begin typing to search or press Enter V Additional Sources				
	Q Type search criteria or press Enter Select Sources	Advanced			0 marked for deletion 0 changed
	No rows found matching criteria. Additional Facilities				

Home Home	• TEST ENVIRONMENT	Pages 11 thru 14 components.	are for the Nut	s, Washers and oth	er	Actions Help Log off
Overview Find Sample Maintain Test Que	ue Receive at Destination Lab	Receive at Lab Unit Review Samples Re	eview Tests			
Sample Record Summary	There	are unsaved changes.			×	
✓ Sample Record: slade202203281	14302				1. Click "Save"	
General	Sample Record: Test(s) may	v not be assigned to Sample Records without a D	Destination Lab association on the Ass	ociations tab.		
Sample Location	✓ Primary Source/Fac	sility				
Additional Information	Select Primary Source	Select Primary Facility				
Sources	Source ID - Source Name			Facility ID - Facility Name		
Associations	00031601 - ST. LOUIS SCR	EW & BOLT (ST LOUIS,MO)				
Contract	Source City			Facility City		
Tests	ST. LOUIS					
	Source Type			Facility Type		
	P - PRODUCER					
	Source Location Description	n		Facility Location Description		
	SMFMI Name					
	Q Begin typing to search of	or press Enter				
	✓ Additional Sources					
	Q Type search criteria or p	oress Enter 🥒 Advanced				
	Select Sources.	2. Click "Select So	urces".			0 marked for deletion 0 changed
	No rows found matching crite	ria.				
	✔ Additional Facilities					

Home Select Sources			▼ P × Log off
Overview F Sample I Q. Type search criteria or press Sample I Select: All None General Enter search criteria above to see Sample Loc Sample Loc	Enter Advanced results or Show first 1	Either search for the source(s) or click "Show first 10".	0 selected
Additional I			Add to Sample Record
Associations	00031601 - ST. LOUIS SCREW & BOLT (ST LOUIS,MO)	•	
Contract Tests	Source City ST. LOUIS	Facility City	
	Source Type P - PRODUCER	Facility Type	
	Source Location Description	Facility Location Description	
	SMFMI Name Q Begin typing to search or press Enter ✓ Additional Sources		
	Q Type search criteria or press Enter Advanced		0 marked for deletion 0 changed
	No rows found matching criteria. Additional Facilities		

Home 🔻	Select Sources					▼ 0 ×	U Log off
Overview F Sample F Sample F General	Q Unyt Select: All None Source ID - Name	Advanced shor 1. Sele	ect the source(s)	for the component(s).	Location Description	1 selected	• 0
Additional I	✓ 00032601 - UNYTITE IN	NC (PERU,ILLI)	P - PRODUCER	PERU			
Sources Association				2. Click "Add	Sample Record".	Add to Sample Record	
Contract		Source City		Facility City			
		ST. LOUIS Source Type P - PRODUCER		Facility Type			
		Source Location Description		Facility Location De	scription		
		SMFMI Name Q Begin typing to search or press Enter V Additional Sources					
		Q Type search criteria or press Enter Select Sources No rows found matching criteria.	Advanced			0 marked for deletion 0) changed
		✓ Additional Facilities					



:	Sample Record Summary		There are unsaved char	nges.			×	
	✓ Sample Record: slade202203281143	802				1	. Click "Save".	Save V ?
	General	Sample Record: Test(s) may not be assigned to	Sample Records without a De	stination Lab association on the Associations	s tab.		
	Sample Location	✓ Primary Source	e/Facility					
	Additional Information	Select Primary Source	ce Select Primary F	acility				
	Sources	Source ID - Source N	ame			Facility ID - Facility Name		
	Associations	00031601 - ST. LOUIS	SCREW & BOLT (ST LO	UIS,MO)				
	Contract	Source City				Facility City		
2. Click '	"Associations".	ST. LOUIS						
		Source Type				Facility Type		
		P - PRODUCER						
		Source Location Des	cription			Facility Location Description		
		SMFMI Name						
		Q Begin typing to se	arch or press Enter					
		✓ Additional Sou	rces					
		Q Type search crite	ria or press Enter 🧧	Advanced				
		Select Sources						0 marked for deletion 0 changed
		Source ID - Name		Source Type	Source City	Location Descri	ption	×
		00032601 - UNYTITI	E INC (PERU,ILLI)	P - PRODUCER	PERU			
		✓ Additional Fac	ilities					



Sample Record Summary		Save Complete	×	
✓ Sample Record: slade202203281143	02			Save 🔻 ?
General	Sample Record: Tesi	(s) may not be assigned to Sample Records without a Destination Lab association on the Associations tab.		
Sample Location				
Additional Information	Q Type search crite	eria or press Enter 🥒 Advanced		
Sources	New	2 Click "Now" twice (2)		0 added 0 marked for deletion 0 changed
Associations	New	-2. Click New twice (2).		
Contract	No rows found match	ng criteria.		
Tests				

Sample Record Summary	Save Complete			×		
✓ Sample Record: slade20220328114	4302			3.	Click "Save	".
General	Sample Record: Test(s) may not be assigned	t to Sample Records without a Destination Lab as	ssociation on the Associations tab.			
Sample Location						
Additional Information	Q Type search criteria or press Enter	Advanced				
Sources					1 20	ded 0 marked for deleti
Associations	New				1 64	
Contract	Association Type *	Association Value * 🔻				
Tests	Ă.	Q Begin typing to search or	press Enter			
1. Select "Des	stination Lab" from th	ne drop down.				

Pages 17 thru 20 are ONLY if you know the specific Contract(s) the tested material is going to. Skip to page 21 Step #3 if unknown.

Home	TEST ENVIRONMENT	Actions Help Log off
Overview Find Sample Maintain Test Queue	Receive at Destination Lab Receive at Lab Unit Review Samples Review Tests	
Sample Record Summary	Save Complete X	
✓ Sample Record: slade20220328114	302	Save 🗸 ?
General		
Sample Location	Q Type search criteria or press Enter Advanced	
Additional Information	Select Contract Project Items Click "Select Contract Project Items".	0 marked for deletion 0 changed
Sources		
Associations	No rows lound matching chiena.	
Contract		
Tests		

Home	Select Contract Project Item Line Numbers	▼ 0 ×	U Log off
Overview F			
v Samp	Q Type search criteria or press Enter Advanced Select: All None	0 selected	- 0
General Sample Loc	Enter search criteria above to see results or Show first 16		
Additional I		Save) changed
Associations	No rows found matching criteria.		
Tests			

Home 🔻	Select Contract Project Item Lir	ne Numbers		▼ (2)	Log off
Overview F					
Sample F	NAME OF TAXABLE PARTY				
🗸 Samp	Q 517112191 Select: All None	Advanced showing 10 1. Select the Contract	Item(s) from the list.	1 selected	- 0
General	Contract	Project	Project Item Line Nbr	Material Set	
Sample Loc Additional I	✔ 517112191 - BRIDGE	517112191 KA 2130-02	63 - STRUCTURAL STEEL (M270) (GR 50WT2)	Structural Steel(M270)(Gr 50WT2) & Faster) changed
Sources					5 changea
Association			2 Click "Save"	Save	
Contract			Z. Olick Dave .		
Tests					

Home Previous My Pages	TEST ENVIRONMENT					Actions Help Log off
Overview Find Sample Maintain Test Queue	Receive at Destination Lab R	eceive at Lab Unit Review Samples R	eview Tests			
Sample Record Summary	Save su	cessful			×	
✓ Sample Record: slade20220328114	302					Save 🗸 🖓
General Sample Location	Q Type search criteria or pre-	is Enter 🥒 Advanced Showing 1 of 1				
Additional Information Sources	Select Contract Project Items.					0 marked for deletion 0 changed
Associations	> Contract		Contract Proje 1	ect Item Material Sets		•
Tests Click the expand	button for the	contract.				

Home	TEST ENVIRONMENT				Actions Help Log off
Overview Find Sample Maintain Test Queu Sample Record Summary	e Receive at Destination Lab Receive at Lab Unit Revi	ew Samples Review Tests		×	
✓ Sample Record: slade2022032811	4302			2. Click "S	ave". Save 🗸 ?
General Sample Location	Q Type search criteria or press Enter d Advance	ed Showing 1 of 1			
Additional Information	Select Contract Project Items				0 marked for deletion 0 changed
Associations	Contract 517112191	C	ontract Project Item Material Se	sts	•
Tests 3. Click "Tests".	Project 517112191 KA 2130-02 ✓ Fed St Proj Num NHPP-0706(125) / 1070 105 KA 2130-02	ltem 071321 - STRUCTURAL STEEI Proj Ln Num 63	. (M270) (GR 50WT2) Work Location	Material Set Name Structural Steel(M270)(Gr 50WT2) & Fasteners Remarks 0	•
1 Enter	Work Location Q Begin typing to search or press Enter	n the contract	Material Ui EACH	nit	
	Represented Quantity		Satisfied F 100.0000	Represented Quantity	
	✓ Remarks Type* Remarks	emark *			
					Q

Home	TEST ENVIRONMENT		Actions	P Help	U Log off
Overview Find Sample Maintain Test Queue	Receive at Destination Lab Receive at Lab Unit Review Samples Review Tests	S			
Sample Record Summary	Save Complete	×			
✓ Sample Record: slade20220328114	302			Save	• ?
General Sample Location	Material FAST_TYPE1 - FASTENERS TYPE 1 BOLT, WASHER, NUT	Sample Type CTA - CERTIFICATION TYPE A			
Additional Information Sources	Q Type search criteria or press Enter Advanced				
Associations Contract	Assign Tests	Click the action button next to "Assign Tests".	0 marked for dele	tion 0 cł	hanged
Tests 2. (No rows found me Assign Default Tests				

Home	TEST ENVIRONMEN	т							Actions H	elp Log off
Overview Find Sample Maintain Test Queue	Receive at Destination	n Lab Receive at Lab Uni	t Review Samples Review Te	sts						
Sample Record Summary		Save Complete					×			
✓ Sample Record: slade202203281143	302						2. Cli	ck "Save".	> Sa	/e 🔻 ?
General	Material					Sample Type				
Sample Location	FAST_TYPE1 - FAST	TENERS TYPE 1 BOLT, WA	SHER, NUT			CTA - CERTIFICATION TYP	PEA			
Additional Information										
Sources	Q Type search crit	eria or press Enter 🖉	Advanced Showing 3 of 3			1. Uncheck	the "MAA	A" box for ea	ich test.	
Associations										
Contract	Assign Tests 🔻						//		0 marked for deletion	0 changed
Tests	1.0	Fasteners Cert	Topeka Regional	Topeka Regional Lab	K	NO	Yes	05 - Test Assigned		•
	1.0	FAST_Chemical Tests	MRC	Chemical Tests Analyti	\swarrow	No	Yes	05 - Test Assigned		•
	Test Number	Test Method	Destination Lab	Lab Unit	MAA 🔻	Required	Default	Test Status		•
	1.0	Fast_Physical Tests	MRC	Physical Tests Metals	K	No	Yes	05 - Test Assigned		





Updated 03/22

Home Home	TEST ENVIRONMENT	Actions Help Log off
Enter Test Results Maintain Test Queue Rev	iew Samples Review Tests Sample Record	
Sample Record Test Summary		
✓ Sample Record ID: slade20220328 ⁴	114302	2. Click "Save". → Save ▼ ?
Test Number: 1.0 Test Method - Description: Fas	steners Cert - Certification for Fasteners	
General	✓ Test Information	
Testers	Test Status	Remarks
Reference Specifications	05 - Test Assigned	0
Retests	Priority	Planned Test Start Date
	Default Test	Test Start Date
	Yes	03/28/2022
	Required Test	Estimated Completion Date
	No	
	Due Date	Actual Completion Date
	#	
	✓ Sample Information	
	Sample Type	Contract ID
	CTA - CERTIFICATION TYPE A	517112191
	Lab Unit	Source
	Topeka Regional Lab - Topeka Regional Lab Unit	00031601 - ST. LOUIS SCREW & BOLT (ST LOUIS,MO)
	Lab Reference Number	Sample Date
	Test Result Value 1. Select the appropriate test result the drop down.	Ilt from This completes the Regional Lab portion. The following pages are for the MRC Lab.

Previous
My Pages
TEST ENVIRONMENT

Home 🔻

Actions Help Log off

On this page: Materials Materials Worksheets Construction Person Overview Reference Data

PROJECT KDOT role for Materials User (Copied from MATERIALUSER)

✓ Materials	•	✓ Construction	?
Acceptance Actions		Change Order	▼
Action Relationships	•	Contract Administration	▼
Daily Source Reports	•	Contract Claims	▼
Find Sample	•	Contract Permits	▼
Mix Design	•	Contract Progress	▼
Product Group Sample Reviewer Assignment	•	Contract Specific Authorities	▼
Sample Records	•	Contract Time	▼
✓ Materials Worksheets	0	Contract Vendor Assets	▼
	U	Contractor Evaluation	•
Enter lest Results		Meetings	Ψ.
Receive Sample at Destination Lab <u>1. Click "Receive Sa</u>	mple at Destination	Lab". te Anoroval Decisions	.
Receive Sample at Lab Unit	▼	Payment Estimates	
Review Samples	▼		
Review Tests	▼		
✓ Person Overview			Save 🔻 ?
Q Type search criteria or press Enter Advanced No Filter V	Jser Reference Employee No Filter No Filter		
			0 marked for deletion 0 changed

Enter search criteria above to see results or Show first 10

✓ Reference Data	?
Administrative Offices	•
Alternate Test Workflow	Ψ.
Code Tables	Ψ.

Home	My Pages 🔻	TEST ENVIRO	DNMENT			Actions Help Log off
Receive at Lab Unit Enter Test R	Results Mainta	in Test Queue	Review Tests Review Samples Sample Review	cords		
Receive Sample at Des	stination La	b				
✓ Receive Sample at Des	tination Lab					Mark As Received 🗸 🤉
Receive at Destination Lab Begin typing to search or press Type search criteria or press	ss Enter	1.	Enter "MRC" as the Destination Lab	Destination Lab.	n, enter the Sample I	D number.
Sample ID *	Sample Date	Material Code	Material Name	Lab Ref Num	Sample Remar	0 added 0 marked for deletion 0 changed
xkarenr517064453kkr14	10/02/2018	002032500	AGGR FOR BIT SURFACE (BM-LA)		1	
xkarenr20190220125320	02/11/2019	002070610	BITUMINOUS MIXTURE (SR-12.5A)		0 🔻	
xkarenr20190305032117	03/04/2019	002070610	BITUMINOUS MIXTURE (SR-12.5A)		0	
C zirkle20200903093343	09/01/2021	074061100	HS STEEL NUT/TY 1/GALV/ASTM A563		1 💌	
C zirkle20200910094612	06/02/2020	022020000	EMULSIFIED ASPHALT (SS-1H)	20-1188 4-3	1 💌	
C zirkle20201110014835	09/21/2020	074041100	HS STEEL BOLT/TY 1/GALV/ASTM A325	20-2041	2 💌	
C zirkle20201110014954	09/21/2021	074041100	HS STEEL BOLT/TY 1/GALV/ASTM A325	20-2041	2	
rickba20210159012336	05/19/2021	25000000	SOIL		0	
orgelio.zamora20210615115738	06/15/2021	CDS	CERTIFIED DEMOLITION SUPERVISOR		0	
zirkle20210630090223	06/30/2021	OFQTestedMatis	Tested Materials	21-0182	0 🔻	
4					>	

Load next 50 rows

Receive Sample at De	estination La						
		b	There are unsaved changes.			×	
eceive at Lab l	Jnit".				2.	Click "Mark As Received".	Mark As R
Receive at Destination Lab							
Q MRC							
Materials and Research Center							
			Destination Lab				
Q slade	<i>2</i> A	Advanced Show	ing 11 of 11 Q MRC				
			Materials and Research Center				
Sample ID *	Sample Date	Material Code	Material Name	Lab Ref Num	Sample Remar		0 added 0 marke
slade20210728070733-1	07/28/2021	074041200	HS STEEL BOLT/TY 1/UNCTD/ASTM A325	21-1139 11-1	0		
slade20210728070733-2	07/28/2021	074041200	HS STEEL BOLT/TY 1/UNCTD/ASTM A325	21-1139 11-1	0 🔻		
		071011000					
slade20210728070733-3	07/28/2021	074041200	HS STEEL BOLITTY 1/UNCTD/ASTM A325	21-1139 11-1	0 🔻		
Image: slade20210728070733-3 Image: slade20210728070733-4	07/28/2021 07/28/2021	074041200	HS STEEL BOLT/TY 1/UNCTD/ASTM A325	21-1139 11-1 21-1139 11-1	0 🔻		
slade20210728070733-3 slade20210728070733-4 slade20210728070733-5	07/28/2021 07/28/2021 07/28/2021	074041200 074041200 074041200	HS STEEL BOLT/TY 1/UNCTD/ASTM A325 HS STEEL BOLT/TY 1/UNCTD/ASTM A325 HS STEEL BOLT/TY 1/UNCTD/ASTM A325	21-1139 11-1 21-1139 11-1 21-1139 11-1			
slade20210728070733-3 slade20210728070733-4 slade20210728070733-5 slade20210728070733-5 slade20210728070733-6	07/28/2021 07/28/2021 07/28/2021 07/28/2021	074041200 074041200 074041200 074041200	HS STEEL BOLT/TY 1/UNCTD/ASTM A325 HS STEEL BOLT/TY 1/UNCTD/ASTM A325 HS STEEL BOLT/TY 1/UNCTD/ASTM A325 HS STEEL BOLT/TY 1/UNCTD/ASTM A325	21-1139 11-1 21-1139 11-1 21-1139 11-1 21-1139 11-1	• 0 • • • • • • • • • • • • • • • • • •		
slade20210728070733-3 slade20210728070733-4 slade20210728070733-5 slade20210728070733-5 slade20210728070733-6 slade20210728070733-7	07/28/2021 07/28/2021 07/28/2021 07/28/2021 07/28/2021	074041200 074041200 074041200 074041200 074041200	HS STEEL BOLT/TY 1/UNCTD/ASTM A325 HS STEEL BOLT/TY 1/UNCTD/ASTM A325 HS STEEL BOLT/TY 1/UNCTD/ASTM A325 HS STEEL BOLT/TY 1/UNCTD/ASTM A325 HS STEEL BOLT/TY 1/UNCTD/ASTM A325	21-1139 11-1 21-1139 11-1 21-1139 11-1 21-1139 11-1 21-1139 11-1 21-1139 11-1	♥ 0 ♥ 0 ♥ 0 ♥ 0 ♥ 0 ♥		
slade20210728070733-3 slade20210728070733-4 slade20210728070733-4 slade20210728070733-5 slade20210728070733-6 slade20210728070733-7 slade20210728070733-8	07/28/2021 07/28/2021 07/28/2021 07/28/2021 07/28/2021 07/28/2021	074041200 074041200 074041200 074041200 074041200 074041200	HS STEEL BOLT/TY 1/UNCTD/ASTM A325 HS STEEL BOLT/TY 1/UNCTD/ASTM A325	21-1139 11-1 21-1139 11-1 21-1139 11-1 21-1139 11-1 21-1139 11-1 21-1139 11-1 21-1139 11-1	0 0 0 0 0 0 0 0 0		
stade20210728070733-3 stade20210728070733-4 stade20210728070733-4 stade20210728070733-5 stade20210728070733-6 stade20210728070733-7 stade20210728070733-8 stade20210728070733-8 stade20210728070733-8	07/28/2021 07/28/2021 07/28/2021 07/28/2021 07/28/2021 07/28/2021 07/28/2021	074041200 074041200 074041200 074041200 074041200 074041200 074041200	HS STEEL BOLT/TY 1/UNCTD/ASTM A325 HS STEEL BOLT/TY 1/UNCTD/ASTM A325	21-1139 11-1 21-1139 11-1 21-1139 11-1 21-1139 11-1 21-1139 11-1 21-1139 11-1 21-1139 11-1 21-1139 11-1			
slade20210728070733-3 slade20210728070733-4 slade20210728070733-4 slade20210728070733-5 slade20210728070733-6 slade20210728070733-7 slade20210728070733-8 slade20210728070733-8 slade20210728070733-8 slade20210728070733-8 slade20210728070733-8 slade20210728070733-8 slade20210728070733-9 slade20210728070733-9	07/28/2021 07/28/2021 07/28/2021 07/28/2021 07/28/2021 07/28/2021 07/28/2021 07/28/2021 02/17/2022	074041200 074041200 074041200 074041200 074041200 074041200 074041200 074041200	HS STEEL BOLT/TY 1/UNCTD/ASTM A325 HS STEEL BOLT/TY 1/UNCTD/ASTM A325 STEEL BOLT/TY 1/UNCTD/ASTM A325 Sand/Sand Gravel Official Quality	21-1139 11-1 21-1139 11-1 21-1139 11-1 21-1139 11-1 21-1139 11-1 21-1139 11-1 21-1139 11-1 21-1139 11-1			

Home Previous	My Pages		ONMENT				Actions Help	U Log off
Receive at Destination Lab	Enter Test Results	Maintain Test Q	Queue Review Tests Review Samples Sample Rec	ords				
Receive Sample at I	_ab Unit							
✓ Receive Sample at	Lab Unit						Mark As Received	- 0
Receive at Lab Unit Q Begin typing to search of Type search criteria or pr	press Enter 🗲 ess Enter 🗲	Advanced Show	Lab Unit	2. IF k	known, enter the Sam	ple ID number.		
Sample ID *	Sample Date	Material Code	Material Name	Lab Ref Num	Sample Remar		0 added 0 marked for deletior	n O changed
xkarenr513091111kkr11	10/01/2018	002032500	AGGR FOR BIT SURFACE (BM-LA)		0			
xkarenr20181029100224kkr1	2 10/01/2018	002032500	AGGR FOR BIT SURFACE (BM-LA)		0 👻			
xkarenr20181029102024kkr1	3 10/01/2018	002032500	AGGR FOR BIT SURFACE (BM-LA)		0 💌			
xkarenr20190220125320	02/11/2019	002070610	BITUMINOUS MIXTURE (SR-12.5A)		0 🔫			
xkarenr20190305032117	03/04/2019	002070610	BITUMINOUS MIXTURE (SR-12.5A)		0 💌			
sashwill20201118094831	11/18/2020	074041200	HS STEEL BOLT/TY 1/UNCTD/ASTM A325		0 🔫			
C zirkle20210426105101	01/01/2021	OFQOGCALS	On Grade Concrete Aggregate (Limestone) Official Quality	21-2589 / QPS	2 💌			
5G21008A Mix Design Subm	ttal 06/01/2021	HMA_12.5A	Hot Mix Asphalt SR/SM-12.5A		0 🔻			
Zirkle20210601010839	06/01/2021	074041100	HS STEEL BOLT/TY 1/GALV/ASTM A325	21-XXXXX	1 💌			
rickba20210608023513	06/08/2021	PCCStructures	PCC Structures and Miscellaneous Construction		0			
•					>			

Load next 50 rows

Home Home		іт				Actions Hel
Receive at Destination Lab Enter Test Results	Maintain Test Queue	Review Tests Review Samples Sa	ample Records			
Receive Sample at Lab Unit		There are unsaved changes.			×	
✓ Receive Sample at Lab Unit						Mark As Received
Q Physical Tests Metals Physical Tests Metals Lab Unit	Advanced Showing 1 of	Lab Unit Q Physical Tests Metals Physical Tests Metals Lab Linit				
Sample ID * Sample Date slade20220328114302 03/23/2022	Material Code Material FAST_TYPE1 FAST	ial Name ENERS TYPE 1 BOLT, WASHER, NUT	Lab Ref Num	Sample Remar 0		0 added 0 marked for deb
n the Sample ID numb	per.					

Home Previous My	Pages TEST ENVIRONMENT		Actions	Help	U Log off
Overview Find Sample Maintain Te	est Queue Receive at Destination Lab Receive at Lab Unit Review Samples Review Tests				
The previous page has unsaved cha	anges. Return to Receive Sample at Lab Unit				×
Sample Record Summary	3. Click "Receive at Lab Unit".				
✓ Sample Record: slade2022	0328114302	2. Click "Save".	\longrightarrow	Save	• ?
General	Sample ID *	Remarks			
Sample Location	slade20220328114302	0			
Additional Information	Material Code - Name	Sample Date			
Sources	Q FAST_TYPE1	03/23/2022			
Associations	FASTENERS TYPE 1 BOLT, WASHER, NUT	Sample Status			
Contract	Lab Reference Number	Received at Destination Lab			
Tests		Sample Type			
	Lot/Heat Number	CTA - CERTIFICATION TYPE A			
1. Ent	ter the Lab Reference Number.	Acceptance Method			
	Lot/Heat Type	ACCP - KDOT Tests And/Or Field Inspection			
	•	Authorized Dr			
	Represented Quantity	Autionized by			
	100.000				
	Represented Quantity Units	Authorized Date			
	Q EACH				
	Each	Revised By			
	Lab Control Number				
	Q CNslade20220328114302	Link To Related Sample ID			
		Q Begin typing to search or press Enter			
	Specimen Number	Linked Related Sample ID			

Home	My Pages TEST ENVIRONMENT					Actions	P Help	U Log off
Receive at Destination Lab Receive Sample of ↓ Receive Sample at	Enter Test Results Maintain Test Queue Ret Lob Lupit Click "Maintain Test (Lab Unit	iew Tests Review Samples Sample Records		3.	Click "Mark As Received".	Mark As Re	aceived	• 8
Receive at Lab Unit Q Begin typing to search o Q slade	r press Enter 1 Advanced Showing 1 of 1	Enter your lab unit. Lab Unit Begin typing to search or pr]					
Sample ID *	Sample Date Material Code Material Nar 03/23/2022 FAST_TYPE1 FASTENER	ie STYPE 1 BOLT, WASHER, NUT	Lab Ref Num MRC 22-001/11-1	Sample Remar 0		0 added 0 marked	for deletion	0 changed
2. Select the Sample I	D.						Sł	howing 1 of 1



Load next 50 rows

Receive at Destination Lab Receive at Lab Unit Enter Test Results Review Tests Review Samples Sample Records

Lab Unit ID

Maintain Test Queue

✓ Maintain Test Queue

Q slade

Save 🔻 ? 1. Click the row action button for your Sample ID.

Ċ

0

Actions Help Log off

slade	_	System Default	Showing 10 of 10			Ľ					
Sidde		System Delaur		Begin typing to search or pr						0 added 0 m	arked for deletion 0 ch
Test Number	Sample ID *	Contracts	Lab Ref Num	Test Method	Test Description	Sample Type	🖋 Reportable 🔻	🖋 MAA 🔻	🖋 Lab Unit 🔻	Received at Lab Unit	🖋 Planned Test Sta
	1.0 slade20210728070733-1	519022262	21-1139 11-1	ASTM F3125	Structural Bolts, Steel, Heat Treated	CTA - CERTIFICATION TY	Yes	Yes	Physical Tests Metals		
	1.0 slade20210728070733-1	519022262	21-1139 11-1	Type A Certification	Type A Cert Authorization	CTA - CERTIFICATION TY	Yes	Yes	Physical Tests Metals		
	1.0 slade20210728070733-2	519022262	21-1139 11-1	ASTM F3125	Structural Bolts, Steel, Heat Treated	CTA - CERTIFICATION TY	Yes	Yes	Physical Tests Metals		
	1.0 slade20210728070733-2	519022262	21-1139 11-1	Type A Certification	Type A Cert Authorization	CTA - CERTIFICATION TY	Yes	Yes	Physical Tests Metals		
	1.0 slade20210728070733-3	519022262	21-1139 11-1	ASTM F3125	Structural Bolts, Steel, Heat Treated	CTA - CERTIFICATION TY	Yes	Yes	Physical Tests Metals		
	1.0 slade20210728070733-3	519022262	21-1139 11-1	Type A Certification	Type A Cert Authorization	CTA - CERTIFICATION TY	Yes	Yes	Physical Tests Metals		
	1.0 slade20210728070733-4	519022262	21-1139 11-1	ASTM F3125	Structural Bolts, Steel, Heat Treated	CTA - CERTIFICATION TY	Yes	Yes	Physical Tests Metals		
	1.0 slade20210728070733-4	519022262	21-1139 11-1	Type A Certification	Type A Cert Authorization	CTA - CERTIFICATION TY	Yes	Yes	Physical Tests Metals		
	1.0 slade20210728070733-5	519022262	21-1139 11-1	ASTM F3125	Structural Bolts, Steel, Heat Treated	CTA - CERTIFICATION TY	Yes	Yes	Physical Tests Metals		
	1.0 slade20210728070733-5	519022262	21-1139 11-1	Type A Certification	Type A Cert Authorization	CTA - CERTIFICATION TY	Yes	Yes	Physical Tests Metals		
	1.0 slade20210728070733-6	519022262	21-1139 11-1	ASTM F3125	Structural Bolts, Steel, Heat Treated	CTA - CERTIFICATION TY	Yes	Yes	Physical Tests Metals		
	1.0 slade20210728070733-6	519022262	21-1139 11-1	Type A Certification	Type A Cert Authorization	CTA - CERTIFICATION TY	Yes	Yes	Physical Tests Metals		
	1.0 slade20210728070733-7	519022262	21-1139 11-1	ASTM F3125	Structural Bolts, Steel, Heat Treated	CTA - CERTIFICATION TY	Yes	Yes	Physical Tests Metals		
	1.0 slade20210728070733-7	519022262	21-1139 11-1	Type A Certification	Type A Cert Authorization	CTA - CERTIFICATION TY	Yes	Yes	Physical Tests Metals		
	1.0 slade20210728070733-8	519022262	21-1139 11-1	ASTM F3125	Structural Bolts, Steel, Heat Treated	CTA - CERTIFICATION TY	Yes	Yes	Physical Tests Metals		
	1.0 slade20210728070733-8	519022262	21-1139 11-1	Type A Certification	Type A Cert Authorization	CTA - CERTIFICATION TY	Yes	Yes	Physical Tests Metals		
	1.0 slade20210728070733-9	519022262	21-1139 11-1	ASTM F3125	Structural Bolts, Steel, Heat Treated	CTA - CERTIFICATION TY	Yes	Yes	Physical Tests Metals	-	
	1.0 slade20210728070733-9	519022262	21-1139 11-1	Type A Certification	Type A Cert Authorization	CTA - CERTIFICATION TY	Yes	Yes	Physical T 📎 💼	% ह	\
	1.0 slade20220328114302	517112191	MRC 22-001/11-1	Fast_Physical Tests	Fasteners Physical Tests - F3125, F606, A307, F959	CTA - CERTIFICATION TY	Yes	No	Physical T Tasks		
•					2. Click "	Views".			Views		
									Open Sam	ble Record	
				2 Click "O	non Sampla Pacara	LTost"			Open Sam	ble Record Test	ļ
				J. CIICK U	pen Sample Record				Testers		

Updated 03/22

Home Previous My	Pages TEST ENVIRONMENT	Actions Hel
Enter Test Results Maintain Test Que	ie Review Samples Review Tests Sample Record	
Sample Record Test Sumr	nary	
✓ Sample Record ID: slade20	220328114302	2. Click "Save".
Test Number: 1.0 Test Method - Descr	ption: Fast_Physical Tests - Fasteners Physical Tests - F3125, F606, A307, F959	
General	Test Information	
Testers	Test Status	Remarks
Reference Specifications	10 - Test in Queue	0
Retests	Priority	Planned Test Start Date
k "Testers".	Default Test	Test Start Date
	Yes	
	Required Test	Estimated Completion Date
	No	m
	Due Date	Actual Completion Date
		
	✓ Sample Information	
	Sample Type	Contract ID
	CTA - CERTIFICATION TYPE A	517112191
	Lab Unit	Source
	Physical Tests Metals - Physical Tests Metals Lab Unit	00031601 - ST. LOUIS SCREW & BOLT (ST LOUIS,MO)
	ab Reference Number	Samie Date
	MRC 22-001/11-1	
	Test Result Value 1. Select the appropriate test result from the drop down	Sample Record Remarks 0

Home 🔻 Previous 🔹 My Pages 🔹		т		Actions	Help	U Log off
Enter Test Results Maintain Test Queue Revi	ew Samples Review	ests Sample Record				
Sample Record Test Summary		Save Complete	×			
 Sample Record ID: slade202203281 	14302				Save	?
Test Number: 1.0 Test Method - Description: Fast	t_Physical Tests - Faste	ers Physical Tests - F3125, F606, A307, F959				
General						
Testers	Q Type search crit	ria or press Enter d Advanced				
Reference Specifications	New	Click "New".	0 added 0 ma	rked for delet	ion 0 ch	anged
Retests						
	No rows found match	ng criteria.				

Home 🔻 Previous 💌 My Pages		т			•	0	Ů
					Actions	Help	Log off
Enter Test Results Maintain Test Queue Re	eview Samples Review	Tests Sample Record					
Sample Record Test Summary		Save Complete		×	_		
✓ Sample Record ID: slade20220326	8114302			3. Click "Save".	\rightarrow	Save	• ?
Test Number: 1.0 Test Method - Description: F	ast_Physical Tests - Faster	ners Physical Tests - F3125, F606, A3	J7, F959				
General							
Testers	Q Type search crit	eria or press Enter 🥒 Advance	1				
Reference Specifications	New			1 added 0	marked for dele	tion 0 c	hanged
Retests	Trades ID & T		Trades Antique Tr				•
1. En	Q Begin troing to	search or press Enter					Ŕ
			2. Enter what action the tester perform	med.			

Home 💌 Previous 💌 My Pages	TEST ENVIRONMENT		Actions	Help Log off
Enter Test Results Maintain Test Queue Rev Sample Record Test Summary	view Samples Review Tests Sample Record Save Complete	1. Click the component	action button.	- 0
Test Number: 1.0 Test Method - Description: Fa	ST_Physical Tests - Fasteners Physical Tests - F3125, F606, A307, F959		Actions	X
General Testers	Q Type search criteria or press Enter 🥒 Advanced Showing 1 of 1		There are no actions available. Tasks Generate Test Results Comparison	
Reference Specifications Retests	New	2. Click "Mark Test Complete".	Mark Test Complete Views	nged
	Q slade Brent Slade	Entered Test Results	Attachments Issues Links	М



Ċ 8 Help Log off Actions

Save 🔻 ?

Receive at Destination Lab Receive at Lab Unit Enter Test Results Maintain Test Queue Review Samples Sample Records

Review Tests

✓ Review Tests

IF known, enter your Sample ID number. Q Type search criteria or press Enter

0 added 0 marked for deletion 0 changed

_	🖋 Reportable 🔻	Lab Control Number	Sample ID *	Lab Ref Num	Test Description	Test Number 🍍	Test Result Value	Test Status	Actual Completion Date	Priority	Due Date	_
0	Yes	CNxkarenr513091111kkr11	xkarenr20181029100224kkr12		CMS Test Results (T_MFGRD)	1.	0 PASS	50 - Test Reviewed by Level 1	10/29/2018			•
0	Yes	CNsashwill20201113032348	sashwill20201113032348		Type A Cert Authorization	1.	0	40 - Test Complete	11/16/2020			▼
0	Yes	CNsashwill20201118094831	sashwill20201118094831		Structural Bolts, Steel, Heat Treated	1.	1	40 - Test Complete	02/10/2022			•
0	Yes	CNrickba20210423061249	rickba20210423061249		Aggregate, Gradation	1.	0	40 - Test Complete	09/13/2021			▼
0	Yes	CNrickba20210427091636	rickba20210427091636		Aggregate, Coarse specific gravity a	1.	0 PAAA	40 - Test Complete	09/13/2021			•
0	Yes	CNrickba20210427092216	rickba20210427092216		Performance Graded Asphalt Binder	1.	0	40 - Test Complete	09/13/2021			•
0	Yes	CNxxjfloyd20210427012128	xxjfloyd20210427012128		Asphalt, Asphalt sampling	1.	0	40 - Test Complete	04/27/2021			•
0	Yes	CNxxjfloyd20210428082416	xxjfloyd20210428082416		PCC Plastic Tests (KT-17, KT-18, KT	1.	0	40 - Test Complete	04/28/2021			▼
0	Yes	CN4G21018B Verification Data	4G21018B Verification Data		HMA Mix Analysis (KT-58, KT-15-III,	1.	0 PASS	40 - Test Complete	06/17/2021			•
0	Yes	CN4G21018BWS Verification Data	4G21018BWS Verification Data		HMA Mix Analysis (KT-58, KT-15-III,	1.	0 PASS	40 - Test Complete	06/23/2021			▼
	4										÷	
	Conorato To	st Doculto Comparison Mad	Tosts Doviow By Loval 1	ark Taste Doviow By Lovel 2 Doguou	Tasta Doquast Datasta							

Load next 6 rows

Home Home	Actions	Help	U Log off
Receive at Destination Lab Receive at Lab Unit Enter Test Results Maintain Test Queue Review Samples Cample Records 3. Click "Review Samples".			
Review Tests			
✓ Review Tests		Save	?
Q slade Advanced showing 1 of 1	d 0 marked	for deletion	0 changed
Reportable Labre Toritrol Number Sample ID * Lab Ref Num Test Description Test Number Test Result Value Test Status Actual Completion Date Priority CNstade2020328114302 stade20220328114302 MRC 22-001/11-1 Fasteners Physical Tests - F3125 F 1.0 PASS 40 - Test Complete 03/28/2022	Du	e Date	- •
Generate Test Results Comparison Mark Tests Review By Level 1 Mark Tests Review By Level 2 Requeue Tests Request Retests		Sh	nowing 1 of 1



Actions Help Log off

Receive at Destination Lab Receive at Lab Unit Enter Test Results Maintain Test Queue Review Tests Sample Records

Review Samples

 Review Samples 									Save 🔻 ?
Q Type search criteria or press	Enter Advanced Snowing 10	Product Group or 53 Q Begin typing to sea	arch or pr	wn, enter the S	Sample	ID num	ber.	0 addec	0 marked for deletion 0 changed
Acceptance Method Test	Number * 🖋 Sample Status * 🗸	Sample ID *	Sample Type	Test Status	Sample Date	Contracts	Lab Ref Num	Test Method	Test Description
ACCP - KDOT Tests And/	1.0 Pending Authorization	rickba20200820011055	ACC - Acceptance	60 - Test Approved by Level 2		519022262-rb2		KT-17	PCC, Sampling plas
ACCP - KDOT Tests And/	1.0 Pending Authorization	rickba20200820011055	ACC - Acceptance	60 - Test Approved by Level 2		519022262-rb2		KT-18	PCC, Air content by 🔻
ACCP - KDOT Tests And/	1.0 Pending Authorization	rickba20200820011055	ACC - Acceptance	60 - Test Approved by Level 2		519022262-rb2		KT-20	PCC, Unit weight bi 🔻
ACCP - KDOT Tests And/	1.0 Pending Authorization	rickba20200820011055	ACC - Acceptance	60 - Test Approved by Level 2		519022262-rb2		KT-21	PCC, Slump 🔻
ACCP - KDOT Tests And/	1.0 Complete	xxjfloyd20201209124713	ACC - Acceptance	10 - Test in Queue	12/09/2020	599550099		PCC Plastic Tests	PCC Plastic Tests (I 🔻
ACCP - KDOT Tests And/	1.0 Complete	xagency2420201214025844	ACC - Acceptance	10 - Test in Queue	12/14/2020	599550013		PCC Plastic Tests	PCC Plastic Tests (I 🔻
ACCP - KDOT Tests And/	1.0 Complete	xagency2520201217032407	ACC - Acceptance	10 - Test in Queue	12/17/2020	599550041		PCC Plastic Tests	PCC Plastic Tests (I 🔻
ACCP - KDOT Tests And/	1.0 Complete	xagency2520210104024956	ACC - Acceptance	10 - Test in Queue	01/04/2021	599550027		PCC Plastic Tests	PCC Plastic Tests (I 🔻
ACCP - KDOT Tests And/	1.0 Complete	xagency2420210114021338	ACC - Acceptance	10 - Test in Queue	01/14/2021	599550005		PCC Plastic Tests	PCC Plastic Tests (I 🔻
ACCP - KDOT Tests And/	1.0 Complete	xagency2520210114021339	ACC - Acceptance	10 - Test in Queue	01/14/2021	599550006		PCC Plastic Tests	PCC Plastic Tests (🔻
4									•

Generate Test Results Comparison Send Test Back to Lab Authorize Samples

Load next 43 rows

Home	Previous	 My Page 	s 🔻 TEST ENVIRONMENT								Actions Hel	p Log
eive at D	Destination Lab	Receive at Lab) Unit Enter Test Results M	aintain Test Queue Revie	w Tests Sample Records							
view												
✓ Revi	view Samples					1.	Click th	e row ac	tion button	for your Samp	le ID.	•
slade	;	2	Advanced Showing 3 of 3	Product Group Q Begin typing to se	earch or pr					0 addi	d 9 marked for dele	etion 0 o
slade Act	cceptance Method	Zest Number	Advanced Showing 3 of 3 Sample Status *	Product Group Q Begin typing to se Sample ID *	earch or pr Sample Type	Test Status	Sample Date	Contracts	Lab Ref Num	0 addi Test Method	d 8 warke d for dele Test Descrij	tion 0
slade Acr CERT	cceptance Method	Zest Number *	Advanced Showing 3 of 3 Advanced Showing 3 of 3 Sample Status * Complete	Product Group Q Begin typing to se Sample ID * slade20210616075727	earch or pr Sample Type CTA - CERTIFICATION TYPE A	Test Status 05 - Test Assigned	Sample Date 06/16/2021	Contracts 518042373	Lab Ref Num	0 adde Test Method Type A Certification	d 0 marked for dele Test Descrip Type A Cert	tion 0
Slade Act CERT CERT	cceptance Method T - Certification T - Certification	Test Number *	 Advanced Showing 3 of 3 Sample Status * Complete Complete 	Product Group Q Begin typing to se Sample ID * slade20210616075727 slade20210616103000	earch or pr Sample Type CTA - CERTIFICATION TYPE A CTA - CERTIFICATION TYPE A	Test Status 05 - Test Assigned 05 - Test Assigned	Sample Date 06/16/2021 06/10/2021	Contracts 518042373 519022262-dew2	Lab Ref Num	0 add Test Method Type A Certification	d Granked for dele Test Descrip Type A Cert	tion 0 otion Authoriz
Acr CERT CERT ACCP	cceptance Method T - Certification T - Certification P - KDOT Tests And/	Zest Number *	Advanced Showing 3 of 3 Sample Status * Complete Complete Complete Complete Complete	Product Group Q Begin typing to sa Sample ID * slade20210616075727 slade2021061607527 slade20210616103000 slade20210706070822	earch or pr Sample Type CTA - CERTIFICATION TYPE A CTA - CERTIFICATION TYPE A ACC - Acceptance	Test Status 05 - Test Assigned 05 - Test Assigned 05 - Test Assigned 05 - Test Assigned	Sample Date 06/16/2021 06/10/2021 Click "Ta	Contracts 518042373 519022262-dew2	Lab Ref Num	0 add Test Method Type A Certification	d 0 marked for dek Test Descrip Type A Cert	otion 0 Authoriz

Send an email to the Submitter of the Sample ID that the sample is Complete.