AWP User Guide for Entering MA Gradations for PCC v5.2 Rev. 01/04/2024

P Log on to AASHTOWare Project [™] × +	~	- 0	×
← → C ▲ Not secure awp.ksdot.org/Account/LogOn	0 , B	☆ 🛛 📧	:
🔇 Intranet 🔇 Specs 🔇 PQLs 🎦 AWP 🔇 CMS Forms 🔇 Documentation Ma 🔇 Part V 🍘 ArcGIS 💠 CARS 🔏 ProjectWise 🔇 Pay to 🗾 BI Portal 🔇 AWP Guides	큕 CIT Signup	큕 Canvas	>>



Version 4.4.11 Revision 056

AASHTOWare ProjectTM and the AASHTOWare ProjectTM logo are registered trademarks of the American Association of State Highway and Transportation Officials. Copyright ©1997-2022 AASHTO.





2) Click on the hyperlink with your Mix Design Number

Home	My Pages 💌		Action	s Help	U Log off
Overview					
Mix Design Summary					
✓ Mix Lesign: 1PW5168A					- ?
General	Mix Design ID*		Remarks		
Component Materials	1PW5168A		1		
Contracts	Mix Design Type		Approval Date		
Specifications	PCC Design Mix - PCC Design Mix Design		06/10/2022		
SMFMI	Description		Approved By		
	1PW5168A-MCM - AIRPORT PLANT #5 (601903)	Q	Q baltazor		
			Baltazor Rita K		
			Effective Date		
	PCCP Mainline non-QC		09/11/2020		
	Source *		Expiration Date		
	Q 00601900				
	MIDWEST CONC MATRLS (MANHATTAN OFFICE)		Status		
			ACTIVE - Active		
		•	he of the Meterial Cod		
	T) Take r	101	te of the Material Cod	9	
	used as	5 W	ell as the Source ID.		
	Vou	\ \/i	Il nood those later		
1	TOU	VVI	וו ווכבע נווכשב ומנכו.		
Click Hor	ne				



On this page: Construction Materials Person Overview External Links Special Provision Overview



✓ Construction	?	✓ Materials	?
Change Order	-	Acceptance Actions	-
Contract Administration	-	Action Relationships	-
Contract Claims	-	Daily Source Reports	-
Contract Permits	-	Find Sample	-
Contract Progress	-	Mix Design	-
Contract Specific Authorities	-	Product Group Sample Reviewer Assignment	-
Contract Time	-	Sample Records	-
Contract Vendor Assets	-		
Contractor Evaluation	-		
Daily Diary	-		

Click Sample Records



1) Enter where you pulled your sample from

2) Select your Geographic Area (The District your project is in)

3) Enter Material Code (Must be the same one from the mix design)



Home • Previous • My Pages •	-	•	C
	Actions	Help	Log off

Overview Find Sample Maintain Test Queue Receive at Destination Lab Receive at Lab Unit Review Samples Review Tests

Sample Record Summary

✓ Sample Record:		Save 🔻 ?
General	Sample Record: Test(s) may not be assigned to Sample Records without a Destination Lab association on the Associations tab.	
Sources/Facilities	✓ Primary Source/Facility	
Associations	Select Primary Source Select Primary Facility	
Sample Location	Source ID - Source Nan	Facility ID - Facility Name
Additional Information	Source City Click Select Primary Source	- Facility City
	Source Type	Facility Type
	Source Location Description	Facility Location Description
	SMFMI Name Q Begin typing to search or press Enter Additional Sources	
	Q Type search criteria or press Enter a Advanced	0 marked for deletion 0 changed
	No rows found matching criteria.	

Home 💌	Select Primary Source					► CO Log off
Overview Fi Sample F Sampl	Q 601903	Advanced Showing 1 of 1	— 1) Enter Sc	ource ID Code		1 selected
General	Source ID - Name		Source Type	Source City	Location Description	
Sample Loc:	✓ 00801903 - MIDWEST CC	DNC MATRLS(AIRPORT PCCP PLT #5)	M - MIX PLANT	MANHATTAN (HOME OFF)		
Sources		2) Select you	ur Producer —	3) Click Add to Sample	e Record ——	Add to Sample Record
Contract		Source City		Facility City		
		Source Type		Facility Type		
		Source Location Description		Facility Location Des	scription	
		SMFMI Name Q Begin typing to search or press Enter Additional Sources				
		Q Type search criteria or press Enter	Advanced			
		Select Sources No rows found matching criteria.				0 marked for deletion 0 changed
		✓ Additional Facilities				

1) Once your source has been entered, click Save.



1)	Enter the name of the ran the t	person who est	actually		
Home Home Home					Actions Help Log off
Overview Find Sample Maintain Test Queu	ue Receive at Destination Lab Receive at Lab	Init Review Samples	Review Tests		
Sample Record Summary	There are unsaved chang	·5.		×	
Sample Record: kody.henrichs202	40104023601				Save 🗸 💎
General	Sample Record: Test(s) may not be assigned to	Sample Records without a	Destination Lab association on the Associ	iations tab.	
Sources	Sample ID*			Remarks	
Associations	kody.henrichs20240104023601			0	2) Click Sove
Contract	Inspector Name			Sample Date	2) Click Save
Tests	Q kody.henrichs			10/04/2022	
Sample Location	Kody Henrichs			Sample Status	
Additional Information	Sampled From			Pending	
	Truck			Sample Type	
	Geographic Area *			VER - Verification	
	02 - DISTRICT 2 - SALINA			Acceptance Method	
	Material Code - Name			ACCP - KDOT Tests And/Or Field Inspection	
	Q PCCPMainline			Authorized By	
	PCCP Mainline non-QC				
	Represented Quantity			Authorized Date	
	350.000				
	Represented Quantity Units			Revised By	
	CUBIC YARD				
	i c J				

3) Click Associations

	•			Actions Help Log off
verview Find Sample Maintain Test Queur	e Receive at Destination Lab Receive at Lab Unit Review !	/ Samples Review Tests		
Sample Record Summary	Save Complete		×	
✓ Sample Record: kody.henrichs2024	40104023601			Save 🔻 ?
General	Sample Record: Test(s) may not be assigned to Sample F	Records without a Destination Lab association on the Associations tab	b.	
Sources				
Associations	Q Type search criteria or press Enter d Advance	ced		
Contract	New			0 added 0 marked for deletion 0 changed
Tests				
Sample Location	No rows found matching criteria.	₋ 1) Click New		
Overview Find Sample Maintain Test Queu	e Receive at Destination Lab Receive at Lab Unit Review St	Samples Review Tests		4) Click Save
Sample Record Summary	2) Select Des	stination Lab in the Associa	ition Type drop-down box	
 Sample Record: kody.henrichs202 	40104023601			Save 🗸 ?
General	Sample Record: Test(s) may not be assigned to Sample Re	(ecords without a Destination Lab association on the Associations tab.		
Sources				
Contract	Auvance	^a 3a) If you	are a KDOT employee, enter	your location
Tests	New			≥letion 0 changed
Sample Location	Association Typ	Association Value *		
Additional Information				×
Auditorial Information	Destination Lab	Q D2A1 Field		× H
	Destination Lab	Q D2A1 Field D2A1 Field Lab (Junction City)		× H
	Previous My Pages	Q D2A1 Field D2A1 Field Lab (Junction City)	UR	×
Home	Previous My Pages Sample Maintain Test Queue Receive at Destination Lab	Q D2A1 Field D2A1 Field Lab (Junction City)	UR	× H
Home	Previous My Pages Sample Maintain Test Queue Receive at Destination Lab R cord Summary	Q D2A1 Field D2A1 Field Lab (Junction City) Receive at Lab Unit Review Samples Review Tests 3b) If yo	ou are a consultant, select Con	sultant Lab
Home Contraction Dverview Find Sample Rev Contraction	Previous My Pages Sample Maintain Test Queue Receive at Destination Lab F cord Summary Record: kody.henrichs20240104023601	Q D2A1 Field D2A1 Field Lab (Junction City) Receive at Lab Unit Review Samples Review Tests 3b) If yo	UR ou are a consultant, select Con	sultant Lab
Home Home Find Sample Re General	Previous My Pages Sample Maintain Test Queue Receive at Destination Lab F cord Summary Record: kody.henrichs20240104023601 Sample Record: Test(s) maintain Test (s) maintain	Q D2A1 Field D2A1 Field Lab (Junction City) Receive at Lab Unit Review Samples Receive at Lab Unit Review Samples Receive at Lab Unit Review Samples B If yo Tay not be assigned to Sample Records without a Destination Lab asso	ou are a consultant, select Con	sultant Lab
Home Home Turnieu Home Turnieu Home Home Home Home Home Home Home Home	Previous My Pages Sample Maintain Test Queue Receive at Destination Lab F Cord Summary Record: kody.henrichs20240104023601 Sample Record: Test(s) ma	Q D2A1 Field D2A1 Field Lab (Junction City) Receive at Lab Unit Review Samples Receive at Lab Unit Review Samples Bay not be assigned to Sample Records without a Destination Lab asso	ou are a consultant, select Con	sultant Lab
Home Home Tind Home Tind Uverview Find Sample Re- Sample I General Sources Associations	Previous My Pages Sample Maintain Test Queue Receive at Destination Lab F Cord Summary Record: kody.henrichs20240104023601 Sample Record: Test(s) ma Q Type search criteria or	Q D2A1 Field D2A1 Field Lab (Junction City) Receive at Lab Unit Review Samples Review Tests B(b) If yo Tay not be assigned to Sample Records without a Destination Lab asso Private Press Enter Advanced	ou are a consultant, select Con	sultant Lab
Home Home Home Find Sample Re General Sources Associations Contract Total		Q D2A1 Field D2A1 Field Lab (Junction City) Receive at Lab Unit Review Samples Review Tests 3b) If yo ay not be assigned to Sample Records without a Destination Lab asso r press Enter Advanced	ou are a consultant, select Con	A sultant Lab
Home Home Home Home Home Home Home Home Home		Q D2A1 Field D2A1 Field Lab (Junction City) Receive at Lab Unit Review Samples Review Tests 3b) If you hay not be assigned to Sample Records without a Destination Lab asso pr press Enter Advanced Association Value • •	ou are a consultant, select Con	A sultant Lab
Home		Q D2A1 Field D2A1 Field Lab (Junction City) Receive at Lab Unit Review Samples Review Tests 3b) If yo ay not be assigned to Sample Records without a Destination Lab asso r press Enter Advanced Associa on Value • • Q Consultant	ou are a consultant, select Con	A sultant Lab
Home Home Home Home Home Home Home Home Home Home Home Home Home Home		Q D2A1 Field D2A1 Field Lab (Junction City) Receive at Lab Unit Review Samples Review Tests 3b) If yo ay not be assigned to Sample Records without a Destination Lab asso r press Enter Advanced Associa on Value * Consultant C	ou are a consultant, select Con	A sultant Lab
Home Home Home Home Home Home Home Home Home	Previous My Pages Sample Maintain Test Queue Receive at Destination Lab F COORd Summary Record: kody.henrichs20240104023601 Gample Record: Test(s) maintain Con Type search criteria on New On Tration	Q D2A1 Field D2A1 Field Lab (Junction City) Receive at Lab Unit Review Samples Review Tests 3b) If yo ray not be assigned to Sample Records without a Destination Lab asso ar press Enter Advanced Associa on Value * • Consultant Consultant Lab	ciation on the Associations tab.	A sultant Lab
Home	Previous My Pages Previous My Pages ISample Maintain Test Queue Receive at Destination Lab ISample Maintain Test Queue Receive at Destination Lab ISample Maintain Test Queue Receive at Destination Lab Record: kody.henrichs20240104023601 Sample Record: Test(s) mu Q Type search criteria or New on New Association Type • • Destination Lab •	Q D2A1 Field D2A1 Field Lab (Junction City) Receive at Lab Unit Review Samples Review Tests 3b) If yo nay not be assigned to Sample Records without a Destination Lab asso r press Enter Advanced Association Value* Consultant C	ciation on the Associations tab.	A sultant Lab

Home

Ho

Overview Find Sample Maintain Test Queue Receive at Destination Lab Receive at Lab Unit Review Samples Review Tests



Sample Record Summary

Sample Location

Additional Information

✓ Sample Record: kody.henrichs20)240104023601	Save 🔻 ?
General	O Ture course advanta course Entre	
Sources	A Type search chiefta of press chieft a Auvanceu	
Associations	Select Contract Project Items 1) Click Select Contract Project Items	0 marked for deletion 0 changed
Contract	No rows found matching criteria.	
Tests		
Sample Location		
Additional Information		

Home						- (<u>ں</u>
	Select Contract Project Item Line	Numbers				×	b Log off
Overview Fi Sample R			2) Ent	ter your Contract Number			
🗸 Sampl	Q 522032252 Select: All None	System Defa	Showing 2 of 2			2 selected	- 0
General	Contract		Project	Project Item Line Nbr	Material Set		
Sample Loca	 2032252 - PAVEMENT PAT 	CHING	KA 8278-01	5 - PCCP JOINT AND CRACK PATCHING (F	ARTIAL D PCCP Patching (Part)		0 shares of
Sources	✓ 022032252 - PAVEMENT PAT	CHING	KA 8278-01	8 - PCCP PATCHING (FULL DEPTH) (13") (5	SOUND) PCCP Patching (Full Depth)		U changed
Associations							
Contract			3) Select all lines that apply	4) Click 3		Save	
							9 (1)
Home 🝷	Previous My Pages					Actions	Help Log off
Overview Fir	nd Sample Maintain Test Queue Rec	eive at Destination Lab	Receive at Lab Unit Review Samples Review Tests				
Sample R	ecord Summary		Save successful	×			
✓ Sample	e Record: kody.henrichs2024010402	3601				8	sve 🔻 ?
General							
Sources		Q Type search criteria	a or press Enter Advanced Showing 1 of 1				
Association	IS	Select Contract Project	t Items			0 marked for deletic	on 0 changed
Contract		> Contract		Contract Project Item Material Sets			-
Tests		522032252		0			

5) Click Tests

_

Page 13 of 24

Previous 💌 My Pages 💌

- - -

Overview Find Sample Maintain Test Queue Receive at Destination Lab Receive at Lab Unit Review Samples Review Tests

8 ዑ -Actions Help Log off

Page 14 of 24

Sample Record Summary		
✓ Sample Record: kody.henrichs20240	104023601	Save 🔻 😯
General	Material	Sample Type
Sources	PCCPMainline - PCCP Mainline non-QC	ACC - Acceptance
Associations		
Contract	Q Type search criteria or press Enter S Advanced	
Tests	Assign Tests	0 marked for deletion 0 changed
Sample Location	No source found an ababient optimiz	1) Click Assign Tests
Additional Information	No rows round matching onena.	
Home	1	Actions Help Log off
Sample Record Maintain Test Queue		
Assign Sample Record Test		
✓ Assign Sample Record Test		0
Progress: Review Required Tests Selec	t Default Tests Select Optional Tests Add Test Runs and Confirm	
 Review Required Tests: 		2) Click the Arrow
No rows found matching criteria.		*
Home	ages 👻	Actions Help Log off
Sample Record Maintain Test Queue		
Assign Sample Record Test		
Assign Sample Record Test Assign Sample Record Test 		0
Assign Sample Record Test Assign Sample Record Test Progress: Review Required Tests	Select Default Tests Select Optional Tests Add Test Runs and Conf	3) Select MA Gradations (Combined) for PCC
Assign Sample Record Test Assign Sample Record Test Progress: Review Required Tests 2 Select Default Tests: Type search criteria or press Enter 	Select Default Tests Select Optional Tests Add Test Runs and Conf	3) Select MA Gradations (Combined) for PCC 3.1) *Note: Depending on how your mix design was entered into AWP, you might have to select MA Gradations (Combined) for PCC-2
Assign Sample Record Test Assign Sample Record Test Progress: Review Required Tests 2 Select Default Tests: Q Type search criteria or press Enter Select: All None	Select Default Tests Select Optional Tests Add Test Runs and Cont Advanced Showing 6 of 6	3) Select MA Gradations (Combined) for PCC 3.1) *Note: Depending on how your mix design was entered into AWP, you might have to select MA Gradations (Combined) for PCC-2
Assign Sample Record Test Assign Sample Record Test Progress: Review Required Tests 2 Select Default Tests: Type search criteria or press Enter Select: All None Test Method 	Select Default Tests Select Optional Tests Add Test Runs and Cont Advanced Showing 6 of 6 Test Description Lab Unit	3) Select MA Gradations (Combined) for PCC 3.1) *Note: Depending on how your mix design was entered into AWP, you might have to select MA Gradations (Combined) for PCC-2
Assign Sample Record Test Assign Sample Record Test Progress: Review Required Tests 2 Select Default Tests: Type search criteria or press Enter Select: All None Test Method KT-23 	Select Default Tests Select Optional Tests Add Test Runs and Cont Advanced Showing 6 of 6 Test Description Lab Unit PCC, Flexural Strength D2A1 Field Lab	3) Select MA Gradations (Combined) for PCC 3.1) *Note: Depending on how your mix design was entered into AWP, you might have to select MA Gradations (Combined) for PCC-2
Assign Sample Record Test Assign Sample Record Test Progress: Review Required Tests C Select Default Tests: C Type search criteria or press Enter Select: All None Test Method KT-23 KT-38	Select Default Tests Select Optional Tests Add Test Runs and Conf Advanced Showing 6 of 6 Test Description Lab Unit PCC, Flexural Strength D2A1 Field Lab PCC, Pavement Density by the Nuclear Me D2A1 Field Lab	3) Select MA Gradations (Combined) for PCC 3.1) *Note: Depending on how your mix design was entered into AWP, you might have to select MA Gradations (Combined) for PCC-2
Assign Sample Record Test	Select Default Tests Select Optional Tests Add Test Runs and Cont Advanced Showing 6 of 6 Test Description Lab Unit PCC, Flexural Strength D2A1 Field Lab PCC, Pavement Density by the Nuclear Me D2A1 Field Lab Profilograph D2A1 Field Lab PCC Remeability, KT 73, KT 70, or AANUT D2A1 Field Lab	3) Select MA Gradations (Combined) for PCC 3.1) *Note: Depending on how your mix design was entered into AWP, you might have to select MA Gradations (Combined) for PCC-2
Assign Sample Record Test	Select Default Tests Select Optional Tests Add Test Runs and Cont Advanced Showing 6 of 6 Test Description Lab Unit PCC, Flexural Strength D2A1 Field Lab PCC, Pavement Density by the Nuclear Me D2A1 Field Lab Profilograph D2A1 Field Lab PCC Permeability- KT-73, KT-79, or AASH1 D2A1 Field Lab MA Gradations (Combined) for PCC D2A1 Field Lab	3) Select MA Gradations (Combined) for PCC 3.1) *Note: Depending on how your mix design was entered into AWP, you might have to select MA Gradations (Combined) for PCC-2 <u>Autofinalize</u> Test Runs 1 Yes
Assign Sample Record Test Assign Sample Record Test Progress: Review Required Tests C Type search criteria or press Enter Select: All None Test Method KT-23 KT-38 KT-46 Permeability PCC MA Gradations PCC MA Gradation PCC	Select Default Tests Select Optional Tests Add Test Runs and Com Advanced Showing 6 of 6 Test Description Lab Unit PCC, Flexural Strength D2A1 Field Lab PCC, Pavement Density by the Nuclear Me D2A1 Field Lab Profilograph D2A1 Field Lab PCC Permeability- KT-73, KT-79, or AASHT D2A1 Field Lab MA Gradations (Combined) for PCC D2A1 Field Lab	3) Select MA Gradations (Combined) for PCC 3.1) *Note: Depending on how your mix design was entered into AWP, you might have to select MA Gradations (Combined) for PCC-2 Autofinalizer Test Runs Test Runs

4) Click the Arrow

→

teres fere and tere and tere and tere and tere and tere and tere and term a	Home	ges 💌				Actions Help Log off
Asign Sample Record Test	Sample Record Maintain Test Queue					
Angene Surges Alexand India Progress Rever Repark Tax Bellet Optional Tests: Select Optional Tests: Image: Select Optional Tests: <td>Assign Sample Record Test</td> <td></td> <td></td> <td></td> <td></td> <td></td>	Assign Sample Record Test					
	✓ Assign Sample Record Test					?
● select Optional Tests: ● select Optional Test: ● select Optional Test:	Progress: Review Required Tests	Select Default Tests Select Optional Tests Add Test Runs	and Confirm			
A state	3 Select Optional Tests:					
Seet: Al Nore Mones fruid matching others	Q Type search criteria or press Enter	a Advanced				0 colocted
Notice the Arrow	Select: All None No rows found	matching criteria.				0 selected
Image: Province Notice Province					1) Click the Arro	ow →
text Wreak with Required Texts Add text Runs and Confirm: Add text Runs and Confirm: v Required Texts to des found matching ordersi. Continue Confirm: v Required Texts Continue Confirm: v Selected Default Texts Continue Confirm: Confirm: Confirm: Confirm: Confirm: Confirm: <						
ample Record Validation Test Quayes Assign Sample Record Test	Home Home	15 •				Actions Help Log off
Assign Sample Record Test A saking Sample Record Test Node Set Runs and Confirm: A dd Test Runs and Confirm: Required Tests Changed Changed Changed Selected Default Tests Selected Default Tests Selected Default Tests Selected Default Tests Selected Default Tests Selected Default Tests Selected Default Tests Selected Default Tests Selected Default Tests Selected Default Tests Selected Default Tests	Sample Record Maintain Test Queue					
	Assign Sample Record Test					
rogess: Review Required Tests Salect Optional Tests Add Test Runs and Confirm:	 Assign Sample Record Test 					?
Add Test Runs and Confirm: Required Tests Convos found matching orderia. Selected Default Tests Contanged Contanged Test Method Test Description Lab Unit Autofinalize Test Method Test Description Lab Unit Autofinalize Test Method Test Method Test Method Test Description Lab Unit Autofinalize Test Method Test	Progress: Review Required Tests	Select Default Tests Select Optional Tests Add Test Runs an	d Confirm			
Required Tests	4 Add Test Runs and Confirm	1:				
lo rous found matching oriteria. Selected Default Tests Condimed Condimed Cond	✓ Required Tests					
lo rous found matching oriteria.						0 changed
 ✓ Selected Default Tests C Maged Test Description Lab Unit Autofinalize Test Runs ▼ PCC MA Gradations (Combined) for PCC D2A1 Field Lab Yes 1 Selected Optional Tests 	No rows found matching criteria.					
Test Method Test Description Lab Unit Autofinalize Test Runs PCC MA Gradations MA Gradations (Combined) for PCC D2A1 Field Lab Yes 1 Selected Optional Tests Ves 0 changed o rows found matching oriteria. O Changed 0 changed	✓ Selected Default Tests					
Test Description Lab Unit Autofinalize Test Runs PCC MA Gradations MA Gradations (Combined) for PCC D2A1 Field Lab Yes 1 Selected Optional Tests 0 changed o rows found matching criteria. Confirm Confirm						0 changed
PCC MA Gradations MA Gradations (Combined) for PCC D2A1 Field Lab Yes 1 Selected Optional Tests 0 changed 0 changed o rows found matching criteria. 2) Click Confirm Confirm	Test Method	Test Description	Lab Unit	Autofinalize	Test Runs 🔻	
Selected Optional Tests O changed to rows found matching criteria. Olick Confirm Confirm	PCC MA Gradations	MA Gradations (Combined) for PCC	D2A1 Field Lab	Yes		1
0 changed	 Selected Optional Tests 					
2) Click Confirm						0 changed
2) Click Confirm	No rows found matching criteria.					
				2) (lick Confirm	Confirm



2) Click KDOT PCC Combined Gradation

Verify all information is correct and scroll down

Sample Record Test	I					
Agency View Summary						
✓ PCC Combined Gradation	Save 🔫 😯					
Sample ID	Sample Type					
kody.henrichs20240104023601	VER					
Inspector ID	Lab Unit					
000210085	D2A1 Field Lab					
Inspector Name	Lab Unit Description					
Kody Henrichs	D2A1 Field Lab Unit (Junction City)					
Mix Plant	Material Code					
00801903	PCCPMainline					
Mix Plant Description	Material Code Description					
MIDWEST CONC MATRLS(AIRPORT PCCP PLT #5)	PCCP Mainline non-QC					
Mix Design	Quantity (Tons)					
1PW5168A	0					
Contract	Project					
522032252	1070-031 KA 6278-01					
Line Number	Item Code					
5	013302					
	Item Code Description					
	PCCP JOINT AND CRACK PATCHING (PARTIAL DEPTH)					
	0 changed					
	▼					
Aggregate Material Source ID Source Name	Mix % Blend					
_						



	YYYYY	YYYY	YYYY	YYYYYY	rrrr) .	÷	÷	v			
۶ ۲	1.1/2"						0	0	0		0	
~	1 1/2)	Ŭ	v	0		0	
7	1"					0	0	0	0		0	
7	3/4"	0.0			~		0	0	1) Complete inputtin	g test	0	
~	1/2"	804.7				35	0	0	results. These results	<u>s must</u>	0	
~	0.07	4 400 4						ļ	be in a red book or a	bound		
, ,	3/8	1,400.1	0.0	0.0		01	U	U	gradation book		U	
~	#4	2,125.1	151.5	54.9		92	6	3	0		0	
7	#8	2,260.7	1,497.3	455.2	~	97	63	21	0		0	
~	#16	2,267.5	2,275.2	1,072.9		98	95	50	0		0	
~	*20	0.000.0		1.010.5				-,				
, ,	#30	2,209.9	2,300.3	1,010.0		90	99	74	U		U	
۲	#50	2,272.6	2,379.5	1,985.0		98	99	92	0		0	
~	#100	2,275.0	2,384.5	2,100.2	~	98	100	97	0		0	
	#200	2,277.1	2,385.1	2,112.3		98.0	99.7	97.7	0.0			
~	2	0.070.4		0.440.0		Ś						
~	Fan	2,278.4	2,380.0	2,113.0)						
۲	Moisture (KT-24)	1.70			~							
4	Grabation Factor	<u> </u>	JUL	uu	uu	6.42	4.62	3.37	0.00			
	Acceptibility (<= 0.3)	2) So	croll to top	of page		0.0	0.0	0.5				
										▼ ()	U	
	Home Previous	My Pages •								Actions Help	Log off	
S	ample Record Test											
/	Agency View Summa	ary										
	✓ PCC Combined Grad	dation								Save	- ?	
-	Sample ID						Sample Type					
kody.henrichs20240104023601												
	000210065 4) Click Sample Record Test					D2A1 Fie	eld Lab		2) Click Sovo			
Inspector Name						Lab Unit	Lab Unit Description			C		
	Kody Henrichs D2A1 Field Lab Unit (Junction City)											
Mix Plant Material Code												
00601903 PCC							ainline					
Mix Plant Description							Material Code Description					
	MIDTEST CONCIMATES(AI	IN ON FOUPPLI #	,			FUUPM				Page 1	9 of 24	



3) Click General

Sample Record Test Su	mmary	Save Comp	lete			×		
 Sample Record ID: kody. 	henrichs2024	010402360	1				Save 🔻 ?	
Test Number: 1.0 Test Method - De	escription: PCC N	MA Gradations		Actions	×			
Testers	✓ Test Infe	rmation				There are no actions available.		
General	Test Status				Remarks	Tasks		
Reference Specifications	05 - Test Assigned		Click Mark Test Complete -		0	Mark Test Complete		
Retests	Priority				Planned Test Start Dar	Views		
						Attachments (U) Issues		
	Default Test					KDOT PCC Combined Gradation_v2 Links		
	Yes				01/04/2024 Estimated Completion Date			
	Required Tes	t						
	No				Actual Completion Date			
	Due Date							
	✓ Sample	Information						
	Sample Type				Contract ID			
	VER - Verification				522032252		1	



Overview Find Sample Maintain Test Queue Receive at Destination Lab Receive at Lab Unit Review Samples Review Tests

Sample Record Summary

Sample Record ID: kody.	henrichs20240104023601		Save 🔻 ?
General	Sample ID*	Remarks	
Sample Location	kody.henrichs20221004125521	0	
Additional Information	Material Code - Name	Sample Date	
Sources	Q PCCPMainline	06/17/2022	
Associations	PCCP Mainline non-QC	Sample Status	
Contract	Lab Reference Number	Complete	
Tests		Sample Type	
	Lot/Heat Number	VER - Verification	
		A constants Mathematic	
	Lot/Heat Type		
		ACCF - ADOT TESIS AIRIOT FIER INSPECTION	
	Represented Quantity	Authorized By	
	350.000	WISYSTEMUSER	
		Authorized Date	
	Represented Quantity Units	01/04/2024	
	begin typing to search of press Enter	Revised By	

1) Verify the Sample Record has been authorized

Notify the KDOT Construction Office once this test is complete. Include the Sample Record Number

For questions about this user guide, email Kody.Henrichs@ks.gov

Page 24 of 24