PQL-VI-CERT. USER GUIDE AGENCY

Next two pages are the same screen.

🖻 🖅 🖻 Contract Daily	Work Rej × 💽 Generate?Guid=b93964e0-t + 🗸	- 🗆 X
\leftarrow \rightarrow \circlearrowright \textcircled{a}	(i) awptest.ksdot.org/#/DailyWorkReport/14983/Summary	
Home Previous	▼ My Pages ▼ TEST ENVIRONMENT	Actions Help Log off
Contract Administration I Find Sample Items	Daily Work Reports Contract Contract Daily Work Reports Contract Materials and Accep ayment Estimate Subcontracts	ptance Actions Contract Progress
Contract Daily Wo	ork Report Summary	
✓ Contract: 5995500	099 - 1.5 HMA OVERLAY 7. Click "Save"	
DWR Date: 05/06/2019	Inspector: dweirich Sequence: 1 Status: Draft	
General Notes 1. Click on the "Acceptance Re	Q Type search criteria or press Enter Image: Advanced Showing 1 of 1 ecords" tab. Image: Advanced Showing 1 of 1	0 changed
Contractor Equipment	√tem in the expand button, category in sequen	ce Num
Contractor Personnel	025324 TRAFFIC CONTROL KA 4644-99 01	1
Postings	Location Sequence Qty Posted Material Set -	Materials 🗸
Acceptance Records	Project 1 0.100 Q 025324 90 Set A	
Force Account Contractors	Material Represented Source Facility 201030000 - TRAF 0.10000 - - SMFMI V Image: Source Facility	•
	Material Units Conversion Reported Ma Cont Est Mat Sat F LS 1.00000 0.10000 1.00000	0.10000
	Action Type Field Inspection Value	



Revised 03/22

🔁 🗧 📴 Contract Daily W	ork Rej ×		- 0	×
\leftarrow \rightarrow \circlearrowright \circlearrowright	awptest.ksdot.org/#/DailyWorkReport/14983/Summary	□ ☆		·
✓ Contract: 59955009	9 - 1.5 HMA OVERLAY		Save 🤝	
DWR Date: 05/06/2019	Inspector: dweirich Sequence: 1	Status: Draft		
General				
Notes	Q Type search criteria or press Enter 🥒 Advanced	Showing 1 of 1		
Contractors On Site			0 change	ь
Contractor Equipment	4 1. Click the expand button	Outron ID Outron New	e enanger	
Contractor Personnel		Category ID Sequence Num	1	
Postings	Location Sequence Qty Posted	Material Set Ma	iterials 🚽	
Acceptance Records	Project 1 0.100	Q 025324 90 Set A 2	Click the row a	ction but
Contractors	Material Represented Source	Facility	¥	
	201030000 - TRAF 0.10000 00008801 - 3	M TR Actions	X	
	SMFMI	Сору		
	Meterial Units Conversion Deported M	Copy DWR Acceptance Records to	Items	
	Material Units Conversion Reported Ma	Create New Sample Record		
	LS 1.00000 0.100	Delete		
	Action Type 🔻	Fi Views		
	DWR AV - Daily Work Report Agency View	Attachments		
3.	Click "Field Acceptance PQL, VI, Cert".	Field Acceptance PQL, VI, Cert		
	Represented Quantity	St Links		
	0.10000	∠ Material		
Wark Leasting -		Source		
		Tracked Issues		
	Q Begin typing to search or press Enter	ACCP - KDOT Tests And/Or Field Insp	pection -	
nttp://awptest.ksdot.org/AgencyVie	ew/88/AgencyViewTemplate?BaseParentModel=DwrAcceptar	Comments 🔻		^

🖻 🗧 🖻 Agency View Summary	× 🖪 Generate?Guid=b93964e0-(+ ∨				×		
\leftarrow \rightarrow \circlearrowright \circlearrowright awp	test.ksdot.org/#/AgencyView/88/AgencyViewTemplate?BaseParentM	Iodel=DwrAcceptanceRecc 🔟 🛠	t l	Ŀ			
		Actio	ons Help	Log off	^		
Dwr Acceptance Record NOTE: Click "DWR Acceptance Record" if you need to enter another one on this DWR or to go back to the DWR and submit it for approval.							
Agency View Summary							
✓ Field Acceptance PQL, VI,	, Cert	4. Click "Save".		- ?			
Sample Record ID	Sample Type						
Visual Inspection							
Y-YES •	lect the appropriate value from the drop dov	wn.					
Type of Certification Received							
C - Type C - Z. Select the appropriate value from the drop down.							
Product is on PQL Number							
02002 - 20.2 - Retroreflective Shee	ting Products (C 3. Select the appropr	riate value from the dro	p down.				
			·				
					↑ ↓		